

Date Tue 02/06/2024

Job #

Weather

6:00 AM

33° 

Clear

Wind: 0 MPH | Precipitation: .0" | Humidity: 93%

12:00 PM

55° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 48%

4:00 PM

63° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 29%

Work Logs

Name	Description
Cavins Environmental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas, temperature and humidity readings were recorded. Third floor stairwell wall, selective demo started. 149 Story time Phase two of cleaning with antimicrobial fog treatment was done. Microbial growth found on the third floor above the balcony.
Total	

General Notes

1. Exterior: Equipment
2 - 20' Job Conex



2. Exterior: Temperature And Humidity



3. Third Floor - Stairwell Wall: Equipment



4. Third Floor - Stairwell Wall: Containment Upon Arrival/Departure



5. Third Floor - Stairwell Wall: Filter Change


6. Third Floor - Stairwell Wall: Temperature And Humidity

7. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



8. Third Floor - Main Area: Filter Change



9. Third Floor - Main Area: Temperature And Humidity



10. Second Floor - Main Area: Equipment
2 - Air Scrubbers
1 - 25' Extension Cord



11. Second Floor - Main Area: Filter Change




12. Second Floor - Main Area: Temperature And Humidity




13. Second Floor - Southeast Corner: Containment Upon Arrival/Departure






14. Second Floor - Southeast Corner: Equipment

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger







15. Second Floor - Southeast Corner: Temperature And Humidity



16. 149 Storytime: Containment Upon Arrival/Departure






17. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Hepa Vacuum
- 1 - Fogger
- 1 - 50' Extension Cord





18. 149 Storytime: Filter Change









19. 149 Storytime: Temperature And Humidity




20. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord



21. First Floor - Main Area: Filter Change





22. First Floor - Main Area: Temperature And Humidity



23. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure






24. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Posts
- 2 - Air Scrubbers
- 2 - Hepa Vacuums
- 1 - 50' Extension Cords
- 1 - Fogger







25. First Floor - Southwest Vestibule: Filter Change



26. First Floor - Southwest Vestibule: Temperature And Humidity








27. First Floor - Southwest Vestibule: Phase Two Hepa Vacuuming And Anti Microbial Cleaning



28. Third Floor - Stairwell Wall: Selective Demo


29. 149 Storytime: Phase Two Hepa Vacuuming And Anti Microbial Cleaning








30. 149 Storytime: Antimicrobial fog Treatment



31. First Floor - Southwest Vestibule: Phase Two Anti Microbial Fog Treatment



- 32. Overall: Equipment
- 29 - Zip Posts
- 16 - Air Scrubbers
- 3 - Hepa Vacuums
- 3 - Foggers
- 3 - 50' Extension Cords
- 2 - 25' Extension Cords

33. Third Floor - Stairwell Wall: Microbial Growth

Additional microbial growth found on sheetrock located above balcony door area.

