

Date Sun 02/11/2024

Job #

Weather

6:00 AM

38° 

Rain, Partially cloudy

Wind: 11 MPH | Precipitation: .07" | Humidity: 87%

12:00 PM

38° 

Rain, Overcast

Wind: 17 MPH | Precipitation: .01" | Humidity: 92%

4:00 PM

36° 

Rain, Overcast

Wind: 19 MPH | Precipitation: .01" | Humidity: 93%

Work Logs

Name	Description
Cavins Group Environmental	Completed fog treatment in stairwell, counted equipment, and changed all filters in the air scrubbers.
Total	

General Notes

1. Exterior: Equipment
2 - 20' Job Conex




2. Exterior: Temperature And Humidity



3. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord




4. First Floor - Main Area: Filter Change



5. First Floor - Main Area: Temperature And Humidity



6. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



7. First Floor - Southwest Vestibule: Equipment
2 - Zip Posts




8. Overall: Equipment



- 14 - Zip Posts
- 8 - Air Scrubbers
- 1 - 50' Extension Cord
- 2 - 25' Extension Cords
- 1 - Fogger

9. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



10. Second Floor - Main Area: Filter Change



11. Second Floor - Main Area: Temperature And Humidity




12. Third Floor - Main Area: Equipment

- 1 - Air Scrubbers
- 1 - 50' Extension Cord



13. Third Floor - Main Area: Filter Change



14. Third Floor - Main Area: Temperature And Humidity




15. Third Floor - Stairwell Wall: Anti Microbial Fog Treatment




16. Third Floor - Stairwell Wall: Containment Upon Arrival/Departure



17. Third Floor - Stairwell Wall: Equipment
 7 - Zip Posts
 2 - Air Scrubbers
 1 - Fogger



18. Third Floor - Stairwell Wall: Temperature And Humidity



19. Third Floor - Stairwell Wall: Filter Change

