

Date Sun 03/10/2024

Job #

Weather

6:00 AM

35° 

Clear

Wind: 4 MPH | Precipitation: .0" | Humidity: 76%

12:00 PM

61° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 35%

4:00 PM

65° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 28%

Work Logs

Name	Description
Cavins Enviromental	Cavins technician arrived on-site and recorded temperature and humidity readings for the exterior, unaffected area, and affected area. Additionally, the technician took moisture and took thermal images. As needed, equipment was removed during the process. All readings have met the drying goal, resulting in the removal of equipment. The technician applied a biocide treatment to all affected areas.
Total	

General Notes

1. Exterior - Temperature and Humidity



2. Unaffected Area - Temperature and humidity




3. Stairwell - Equipment
1 - Axial Fan
1 - DHU



4. Stairwell - Temperature and Humidity






5. Stairwell - Overall Equipment




6. Stairwell- Moisture readings
All readings have dropped to drying goal



7. Stairwell - Thermal Imaging
Thermal Imaging shows no sign of moisture



8. Stairwell - Equipment Removed



9. Third Floor - Stairwell wall: Thermal imaging
No signs of moisture



10. Third Floor - Stairwell wall: Moisture Readings



11. Biocide treatment of affected areas

