

Date Sat 04/06/2024

Job #

## Weather

6:00 AM

63° 

Clear

Wind: 18 MPH | Precipitation: .0" | Humidity: 56%

12:00 PM

70° 

Partially cloudy

Wind: 26 MPH | Precipitation: .0" | Humidity: 57%

4:00 PM

76° 

Partially cloudy

Wind: 24 MPH | Precipitation: .0" | Humidity: 53%



## Work Logs


Name	Description
Cavins Environmental	Cavins technicians performed a visual and thermal inspection due to weather conditions. Signs of water intrusion were found in several areas of the library; however, the water content wasn't considerable enough for structural drying equipment to be set up.
Total	

## General Notes

### 1. Second Floor - Common Area:

Water intrusion present by bay windows on the south side building, not enough water for structural drying equipment to be set.





**2. Second Floor - Staff Kitchen:**

Cavins technicians removed the insulation from the far-left window on the North side of room and found that the insulation contained no moisture. Insulation was bagged to be removed, however there were about two gallons of water collected on a trashcan placed below leak.





**3. Stairwell:**

Signs of water intrusion were found on the fourth-floor landing by the roof top access door.



**4. First Floor - Children's Area:**

Water intrusion signs were found on ceiling tiles underneath the green roof and above bay windows on the south side of the building.



5. 305 - Pioneer:

Water intrusion signs were found on the SW corner of the ceiling grid.

