

Date Wed 04/03/2024

Job #

## Weather

6:00 AM

42° 

Clear

Wind: 5 MPH | Precipitation: .0" | Humidity: 69%

12:00 PM

57° 

Clear

Wind: 24 MPH | Precipitation: .0" | Humidity: 32%

4:00 PM

63° 

Clear

Wind: 16 MPH | Precipitation: .0" | Humidity: 25%

## Work Logs

Name	Description
Cavins Enviromental	Cavins technicians performed air quality testing in all common areas and areas of concern. Temperature and humidity readings were recorded. A bulk sample was taken from Room 301 - Oklahoma, and a tape lift was taken from Room 115. Containment was set up outside Room 301 - Oklahoma as a measure to mitigate cross-contamination.
Total	

## General Notes

### 1. 115 Temperature and Humidity.



### 2. 115 Air Quality Testing:

A spore trap sample was taken.



**3. First Floor Temperature and Humidity.**



**4. First Floor Air Quality Testing:**

A spore trap sample was taken.



**5. Second Floor Temperature and Humidity.**



**6. Second Floor Air Quality Testing:**

A spore trap sample was taken.



**7. Children's Area Temperature and Humidity.**



**8. Children's Area Air Quality Testing:**

A spore trap sample was taken.



**9. Third Floor:**

Temperature and humidity.



**10. 115:**

Cavins technicians inspected wall cavities and there were no visible signs of water intrusion or microbial

growth.

**11. 115:**

A tape sample was taken.



**12. Stairwell:**

Temperature and humidity.



**13. Stairwell Air Quality Testing:**

A spore trap sample was taken.



**14. Third Floor Air Quality Testing:**

A spore trap sample was taken.



**15. First Floor:**

Cavins technicians inspected area and found no visible signs of water damage or microbial growth.


**16. Second Floor:**

Cavins technicians inspected area and found no visible signs of water damage or microbial growth.

**17. Third Floor:**


Cavins technicians inspected the area and found that in room 301 Oklahoma there was water damage to the paint/drywall. It is recommended to cut the compromised drywall out or do a wall puncture.

Note: A bulk sample was taken.



**18. 301 - Oklahoma - Air Quality Testing:**

A spore trap sample (wall puncture) was taken.



**19. 301 - Oklahoma - Temperature and Humidity.**












20. Exterior Temperature and Humidity.

21. Exterior Air Quality Testing:

A spore trap sample was taken.

22. 301 - Oklahoma:

Containment and a changing room/chamber were built over main access points in room 301.



23. 301 - Oklahoma - Equipment count:

2 Air Scrubbers.

