

Date Tue 04/02/2024

Job #

## Weather

6:00 AM

46° 

Overcast

Wind: 17 MPH | Precipitation: .0" | Humidity: 81%

12:00 PM

47° 

Overcast

Wind: 23 MPH | Precipitation: .0" | Humidity: 70%

4:00 PM

57° 

Partially cloudy

Wind: 20 MPH | Precipitation: .0" | Humidity: 54%

## Work Logs

Name	Description
Cavins Environmental	A Cavins technician conducted a site inspection on all three floors and the stairwell of the building due to the rainy weather the previous day. This inspection also included areas where successful remediation had been performed previously. The technician used thermal imaging and visual inspection techniques, which did not reveal any signs of water intrusion, except for the stairwell on the landing by the roof access door. As a preventative measure, a biocide was applied in the stairwell area and in the children's area due to a musty smell.
Total	

## General Notes

### 1. Biocide:




A biocide treatment was applied in the children's area and on the second and third floor landings of the stairwell as a preventative measure against future microbial growth.





**2. Stairwell:**

A small puddle was noticed in the stairwell.



### 3. Children's Area:

Note: Stale smell present in this area