

Date Fri 01/12/2024

Job #

Weather

6:00 AM

17° 

Partially cloudy

Wind: 27 MPH | Precipitation: .51" | Humidity: 67%

12:00 PM

28° 

Clear

Wind: 21 MPH | Precipitation: .0" | Humidity: 44%

4:00 PM

38° 

Clear

Wind: 13 MPH | Precipitation: .0" | Humidity: 33%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Demo continued in the second floor southeast corner Phase one cleaning began in the stairwell. Investigative demo continued in room 311.
Total	

General Notes

- 311 Local History: Equipment
 - 2 - Air Scrubbers
 - 1 - Fogger
 - 1 - Hepa Vac





2. 311 Local History: Containment Upon Arrival/Departure



3. 311 Local History: Filter Change



4. 311 Local History: Temperature and Humidity




5. 305 Pioneer: Containment Upon Arrival/Departure




6. 305 Pioneer: Equipment

4 - Zip Posts



7. 303 Storage: Containment Upon Arrival/Departure




8. 303 Storage: Equipment

2 - Zip Posts



9. Third Floor - Main Area: Equipment
1 - Air Scrubber
1 - 50 Ft Extension Cord




10. Third Floor - Main Area: Filter Change



11. Third Floor - Main Area: Temperature and Humidity




12. 201A Staff Only: Containment Upon Arrival/Departure



13. 201A Staff Only: Equipment

10 - Zip Posts




14. Second Floor - Main Area: Equipment

2 - Air Scrubbers
1 - 25' Extension Cord



15. Second Floor - Main Area: Filter Change









16. Second Floor - Main Area: Temperature and Humidity



17. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cord
- 3 - 50' Extension Cord
- 4 - Hepa Vac
- 1 - Fogger
- 1 - Zip Post



18. Stairwell: Containment Upon Arrival/Departure




19. Stairwell: Filter Change



20. Stairwell: Temperature and Humidity



21. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



22. Second Floor - Southeast Corner: Temperature and Humidity




23. Second Floor - Southeast Corner: Equipment






- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension Cord







24. Second Floor - Southeast Corner: Filter Change



25. Second Floor -Southeast Corner: Remediation


Demo continued on the underside of the soffit (overhang) and in areas on top of the soffit (overhang) visible microbial growth is seen around the window area and spread out to the underside, all of the affected areas were removed.






26. Stairwell -Phase 1 Cleaning





27. First Floor - Bay Window's (Children's Area): Equipment


- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50 Ft Extension Cord



28. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure



29. First Floor - Bay Window's (Children's Area): Filter Change




30. First Floor - Bay Window's (Children's Area): Temperature and Humidity



31. 149 Storytime: Equipment

- 2 - Air Scrubbers
- 5 - Zip Posts








32. 149 Storytime: Containment Upon Arrival/Departure



33. 149 Storytime: Temperature and Humidity



34. 149 Storytime: Filter Change



35. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure





**36. First Floor - Southwest Vestibule:
Equipment**

- 2 - Air Scrubbers
- 2 - Zip Posts



37. First Floor - Southwest Vestibule: Filter Change





38. First Floor - Southwest Vestibule: Temperature and Humidity



39. SO 115: Containment Upon Arrival/Departure







40. SO 115: Antimicrobial Fog Treatment









41. SO 115: Equipment

- 9 - Air Scrubbers
- 1 - Zip Post



42. SO 115: Filter Change





43. SO 115: Temperature and Humidity



44. First Floor - Main Area: Equipment

2 - Air Scrubbers



45. First Floor - Main Area: Temperature and Humidity




46. First Floor - Main Area: Filter Change



47. Children's Area - Main Entrance: Equipment

3 - Air Scrubbers
10 - Zip Posts



48. Children's Area - Main Entrance: Containment Upon Arrival/Departure



49. Children's Area - Main Entrance: Temperature and Humidity





50. Children's Area - Main Entrance: Filter Change



51. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Fogger



52. Garage: Containment Upon Arrival/Departure



53. Garage: Temperature and Humidity



54. Garage: Filter Change



55. Second Floor- Southeast Corner: Water Trails


Visible water trails can be seen around 3 windows and above drop down ceiling inside exterior soffit area.





56. Exterior: Equipment

2 - 20' Conex Boxes



57. Exterior: Temperature and Humidity



58. Overall: Equipment

- 41 - Air Scrubbers
- 72 - Zip Posts
- 5 - Foggers
- 5 - Hepa Vac
- 2 - 25 Ft Extension Cords

8 - 50 Ft Extension Cords
3 - 100 Ft Extension Cords

59. 311 Local History: Water Trails

