

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 01/24/2024

Job #

## Weather

6:00 AM

38°

Overcast

Wind: 4 MPH | Precipitation: .0" | Humidity: 98%

12:00 PM

44°

Overcast

Wind: 2 MPH | Precipitation: .0" | Humidity: 93%

4:00 PM

43°

Overcast




Wind: 8 MPH | Precipitation: .0" | Humidity: 95%




## Work Logs

Name	Description
Cavins Environmental	Cavins Group took temperature and humidity readings, suited up in proper PPE, and changed pre filters in air scrubbers. Cleaning process continued in 311 Local History along with Anti Microbial Fog Treatment. Remediation continued on Second Floor - Southeast Corner.
Total	

## General Notes



### 1. 311 Local History: Phase Two Hepa Vacuuming And Cleaning





## 2. 311 Local History: Equipment

- 2 - Air Scrubbers
- 2 - Hepa Vacuums
- 1 - 50' Extension Cord
- 1 - 25' Extension Cord
- 1 - Fogger









## 3. 311 Local History: Phase Two Anti Microbial Fog Treatment



#### 4. 311 Local History: Containment Upon Arrivel/Departure



#### 5. 311 Local History: Filter Change



#### 6. 311 Local History: Temperature And Humidity



### 7. Exterior: Equipment


2 - 20' Job Conex



### 8. Exterior: Temperature And Humidity







### 9. Second Floor - Southeast Corner: Containment Upon Arrival/Departure







**10. Second Floor - Southeast Corner: Equipment**  
22 Zip Posts  
6 Air Scrubbers





11. Second Floor - Southeast Corner: Filter Change






12. Second Floor - Southeast Corner: Temperature And Humidity



**13. Third Floor - Main Area: Equipment**

- 1 - Air Scrubber
- 1 - 50' Extension Cord



**14. Third Floor - Main Area: Filter Change**



**15. Third Floor - Main Area: Temperature And Humidity**



**16. Second Floor - Main Area: Equipment**

- 2 Air Scrubbers
- 1 25' Extension Cord



**17. Second Floor - Main Area: Filter Change**






**18. Second Floor - Main Area: Temperature And Humidity**



**19. 149 Storytime: Containment Upon Arrival/Departure**



- 20. 149 Storytime: Equipment**
- 5 Zip Posts
- 2 Air Scrubbers




**21. 149 Storytime: Filter Change**



**22. 149 Storytime: Temperature And Humidity**





**23. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure**



**24. First Floor - Bay Windows (Children's Area): Equipment**


- 12 - zip post
- 4 - Air Scrubbers
- 2 - hepa vacs
- Fogger
- 2 - 50 ft extension cord





**25. First Floor - Bay Windows (Children's Area): Filter Change**










**26. First Floor - Bay Windows (Children's Area): Temperature And Humidity**



**27. First Floor - Main Area: Equipment  
2 Airscrubbers**



**28. First Floor - Main Area: Filter Change**



**29. First Floor - Main Area: Temperature And Humidity**



**30. Main Entrance - Children's Area: Containment Upon Arrival/Departure**

**31. Main Entrance - Children's Area: Equipment**

- 3 - Air Scrubbers
- 10 - Zip Posts

**32. Main Entrance - Children's Area: Filter Change**

**33. Main Entrance - Children's Area: Temperature And Humidity**

**34. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**

**35. First Floor - Southwest Vestibule: Equipment**

- 2 - Air Scrubbers
- 2 - Zip Posts

**36. First Floor - Southwest Vestibule: Filter Change**


**37. First Floor - Southwest Vestibule: Temperature And Humidity**

**38. First Floor - Bay Windows (Children's Area): Antimicrobial fog Treatment**




**39. First Floor - Bay Windows (Children's Area): Selective demo and phase one cleaning**
























40. Second Floor - Southeast Corner: phase 1 cleaning







41. Fogging- All common areas of all three floors have been fogged as a preventative measure due to moisture entering building from recent rain fall.







- 42. Overall Equipment:**  
24 - Air Scrubbers  
51 - Zip Posts  
4 - 50' Extension Cords  
2 - 25' Extension Cords