

Date Fri 01/26/2024

Job #

Weather

6:00 AM

43° 

Overcast

Wind: 5 MPH | Precipitation: .0" | Humidity: 96%

12:00 PM

45° 

Rain, Overcast

Wind: 8 MPH | Precipitation: .0" | Humidity: 94%

4:00 PM

44° 

Rain, Overcast

Wind: 8 MPH | Precipitation: .01" | Humidity: 93%

Work Logs

Name	Description
Cavins Environmental	Cavins Group Arrived on-site, took Temperature and Humidity readings of affected areas, main areas and exterior. Cavins Technicians suited up in proper PPE and changed all pre filters in air scrubbers within containment and in the main areas. Anti-microbial fog treatment was done in 311 Local History and First Floor - Bay Windows. Cleaning phase and Anti-Microbial fog treatment was started in Children's Area - Main Entrance. Remediation started in First Floor - Southwest Vestibule.
Total	

General Notes

1. 149 Storytime: Containment Upon Arrival/Departure



2. 149 Storytime: Equipment

- 2 - Air Scrubbers
- 5 - Zip Post



3. 149 Storytime: Filter Change



4. 149 Storytime: Temperature And Humidity



5. 311 Local History: Antimicrobial Fog Treatment




6. 311 Local History: Containment Upon Arrival/Departure



7. 311 Local History: Equipment
2 - Air Scrubbers
1 - Fogger



8. 311 Local History: Filter Change



9. 311 Local History: Temperature And Humidity



**10. Exterior: Equipment
2 - 20 Ft Conex**



11. Exterior: Temperature And Humidity



12. First Floor - Bay Windows (Children's Area): Anti Microbial Fog Treatment



13. First Floor - Southwest Vestibule: Remediation

Technicians removed plywood decking on top of vestibule with microbial growth present. Technicians hand sanded all affected areas and hepa vacuumed.








14. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure



15. First Floor - Bay Window's (Children's Area): Filter Change






16. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - Fogger
- 2 - 50' Extension Cords












17. First Floor - Bay Window's (Children's Area): Temperature And Humidity



18. First Floor - Main Area: Equipment
 3 - Air Scrubbers
 1 - 25 Ft Extension Cords




19. First Floor - Main Area: Filter Change



20. First Floor - Main Area: Temperature And Humidity




21. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



22. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers
- 1 - Hepa Vac
- 1 - Fogger
- 1 - 50 Ft Extension Cord



23. First Floor - Southwest Vestibule: Temperature And Humidity



24. First Floor - Southwest Vestibule: Filter Change




25. Main Entrance - Children's Area: Containment Upon Arrival/Departure




26. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - Fogger
- 3 - Hepa Vacuums
- 3 - 50' Extension Cord



27. Main Entrance - Children's Area: Filter Change



28. Main Entrance - Children's Area: Temperature And Humidity



29. Overall: Equipment

- 25 - Air Scrubbers
- 50 - Zip Post
- 8 - Hepa Vac
- 3 - Foggers
- 3 - 100 Ft Extension Cords
- 12 - 50 Ft Extension Cords
- 2 - 25 Ft Extension Cords
- 2 - 20 Ft Conex




30. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers

1 - 25 Ft Extension Cord



31. Second Floor - Main Area: Filter Change



32. Second Floor - Main Area: Temperature And Humidity



33. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



34. Second Floor - Southeast Corner: Equipment





22 - Zip Post






6 - Air Scrubbers

3 - 100 Ft Extension Cords

5 - 50 Ft Extension Cords


4 - Hepa Vac







35. Second Floor - Southeast Corner: Filter Change






36. Second Floor - Southeast Corner: Temperature and Humidity



37. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50 Ft Extension Cord




38. Third Floor - Main Area: Filter Change



39. Third Floor - Main Area: Temperature And Humidity




40. Main Entrance - Children's Area: Phase One Hepa Vacuuming And Cleaning








41. Main Entrance - Children's Area: Phase One Anti Microbial Fog Treatment




42. Main Entrance - Children's Area: Phase Two Hepa Vacuuming And Cleaning





43. Main Entrance - Children's Area: Phase Two Anti Microbial Fog Treatment



44. First Floor - Southwest Vestibule: Anti Microbial Fog Treatment

