

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Fri 02/16/2024

Job #

## Weather

6:00 AM

48°

Partially cloudy

Wind: 20 MPH | Precipitation: .0" | Humidity: 94%

12:00 PM

46°

Partially cloudy

Wind: 20 MPH | Precipitation: .0" | Humidity: 49%

4:00 PM

46°

Clear


Wind: 24 MPH | Precipitation: .0" | Humidity: 46%






## Work Logs

Name	Description
Cavins Environmental	Following the remediation process, Cavins technicians removed all damaged ceiling tiles. They thoroughly cleaned the common areas, eliminating debris and dirt. Additionally, the contents from the conex were relocated inside the building. To prevent cross-contamination and enhance air quality, an anti-microbial treatment fog was applied.
Total	





## General Notes

### 1. Anti Microbial Fog Treatment









2. Removal of cut ceiling tiles



3. Cavins technicians removed boxes from the Connex and placed them inside the garage area.



4. Cavins technicians cleaned the areas that had dust and debris on the floor.



5. First Floor - Main Area: Equipment
  - 3 - Air Scrubbers
  - 1 - 25' Extension Cord
6. Second Floor - Main Area: Equipment
  - 1 - Air Scrubber
  - 1 - 25' Extension Cord
7. Third Floor - Main Area: Equipment
  - 1 - Air Scrubber
  - 1 - 50' Extension Cord