

Date Fri 03/01/2024

Job #

Weather

6:00 AM

34° 

Overcast

Wind: 14 MPH | Precipitation: .0" | Humidity: 95%

12:00 PM

45° 

Overcast

Wind: 9 MPH | Precipitation: .0" | Humidity: 76%

4:00 PM

57° 

Clear

Wind: 10 MPH | Precipitation: .0" | Humidity: 57%


Work Logs

Name	Description
Cavins Environmental	Following the intervention by Envelope consultants, Cavins technician conducted air quality testing in both areas of concern and common areas. The purpose was to assess spore disturbance. A total of 12 air spore trap samples were taken.
Total	

General Notes

1. Third Floor - Common Area: Air quality testing

One spore trap sample was taken.




2. Third Floor - 305 Pioneer Room: Air quality testing

One spore trap sample was taken.



3. Exterior: Air quality testing

One spore trap sample was taken.



4. Second Floor - Common Area: Air quality testing

One spore trap sample was taken.



5. Second Floor - Room 201A: Air quality testing

One spore trap sample was taken.



6. Second Floor - Bay Window: Air quality testing

One spore trap sample was taken.



7. Stairwell: Air quality testing

One spore trap sample was taken.




8. First Floor - Common Area: Air quality testing

One spore trap sample was taken.



9. First Floor - Vestibule Area: Air quality testing

One spore trap sample was taken.



10. First Floor - Children's Area: Air quality testing

One spore trap sample was taken.



11. First Floor - Bay Window: Air quality testing

One spore trap sample was taken.



12. First Floor - Room 115: Air quality testing

One spore trap sample was taken.

