



1839 Atchison Drive
Norman
OK
USA

Central Library: 11/16/23-11/19/23

Claim Id

City of Norman - Central Library

Date of Loss

Nov 16, 2023

Date Claim Created

Nov 16, 2023

Address

103 West Acres Street, Norman, OK,
USA

Policyholder Name

City of Norman - Central Library



Table of Contents

General Notes	4
First Floor - Main Area	12
Overview Photos	12
Room Notes	13
Garage	28
Overview Photos	28
Room Notes	29
115 - Staff Only	35
Overview Photos	35
Room Notes	35
Contents - Room 115 - Staff Only	49
Overview Photos	49
Contents - Storage Room: 137	49
Overview Photos	49
Room Notes	49
Contents: (44)	50
First Floor - Southwest Vestibule	55
Overview Photos	55
Room Notes	55
149 - Storytime	62
Overview Photos	62
Room Notes	62
First Floor - Bay Windows (Children's Area)	71
Overview Photos	71
Room Notes	71
Second Floor - Main Area	85
Overview Photos	85
Room Notes	85
201A - Staff Only	98
Overview Photos	98
Room Notes	99
Second Floor - Bathroom	112
Overview Photos	112
Room Notes	112

Second Floor - Southeast Corner	118
Overview Photos	118
Room Notes	118
Second Floor - South Windows	140
Overview Photos	140
Room Notes	140
Third Floor - Main Area	141
Overview Photos	141
Room Notes	141
305 - Pioneer Room	157
Overview Photos	157
Room Notes	157
Southwest Stairwell	171
Overview Photos	171
Room Notes	171

General Notes

**11/16/23 - Exterior
Temperature and Humidity**



**11/16/23 - Second Floor
Temperature and Humidity**



**11/16/23 - Third Floor
Temperature and Humidity**



11/16/23 - Air Scrubbers

All air scrubbers were turned on at 12 pm to start the decontamination process.

11/16/23 - Additional Inspection - Second Floor Southeast Side



11/16/23: 1 - Box Truck



11/16/23 - First Floor Interior Temperature and Humidity



11/17/23 - 1st Floor Interior Temperature and Humidity



11/17/23 - 2nd Floor Morning Temperature and Humidity



11/17/23 - 3rd Floor Temperature and Humidity



11/17/23 - Exterior Temperature and Humidity



11/17/23 - Additional Inspection Children's Area



11/18/23 - 1st Floor Morning Temperature and Humidity



11/18/23 - 2nd Floor Morning Temperature and Humidity



11/18/23 - Morning Exterior Temperature and Humidity



11/17/23 - Equipment



11/18/23 - 3rd Floor Morning Temperature and Humidity



11/18/23 - Equipment: 1 -
Box Truck



11/18/23 - 1st Floor Evening Temperature and Humidity



11/18/23 - 3rd Floor Evening Temperature and Humidity



11/18/23 - 2nd Floor Evening Temperature and Humidity



**11/19/23 - First Floor
Temperature and Humidity**



**11/19/23 - Second Floor
Temperature and Humidity**



**11/19/23 - Third Floor
Temperature and Humidity**



**11/19/23 - Equipment on
Site: 1 - Box Truck**



**11/19/23 - Exterior
Temperature and Humidity**



Overall Equipment Count - 11/16/23

- Air Scrubbers - 31
- Gator Guard - 7 (Areas)
- Sticky Mat - 8
- Zip Post - 52
- 100' Extension Cord - 1
- Box Truck - 1

Overall Equipment Count - 11/17/23

- Air Scrubbers - 35
- Gator Guard - 7 (Areas)
- Sticky Mat - 8
- Zip Post - 52
- 100' Extension Cord - 1

Box Truck - 1

Overall Equipment Count - 11/18/23

Air Scrubbers - 35
Gator Guard - 7 (Areas)
Sticky Mat - 8
Zip Post - 52
100' Extension Cord - 1
Box Truck - 1

Overall Equipment Count 11/19/23

Air Scrubbers - 35
Gator Guard - 7 (Areas)
Sticky Mat - 8
Zip Post - 52
100' Extension Cord - 1
Box Truck - 1

11/16/23 - Daily Synopsis

Cavins Group crews arrived on site, and all crew members suited up in appropriate PPE. A fogging of the entire building was performed with an antimicrobial solution. Air Scrubbers were placed in all common areas and turned on. Containments began being set in the contaminated areas, with air scrubbers placed in each containment area. Another fogging was performed at 12 PM, followed by one more fogging that evening, for a total of three rounds of fogging with an antimicrobial solution. Temperature and humidity readings were taken in all common areas and outside.

11/17/2023 - Daily Synopsis

Cavins Group crews arrived onsite, and all crew members suited up in PPE prior to entering the building. Temperature and humidity readings were taken in the main area in all three levels of the building, as well as an exterior reading. The entire building was fogged with an antimicrobial solution in the morning, the afternoon, and the evening, for a total of three times. All equipment ran throughout the night and filters were changed today. Cavins Group continued working on containing the affected areas. Due to multiple areas with new microbial growth findings, some containments had to be extended, causing the containment setup process to be extended longer than originally planned.

11/18/23 - Daily Synopsis


Cavins Group crews arrived onsite, and all crew members suited up in proper PPE prior to entering the building. All air scrubber filters were changed upon arrival. Cavins crew members continued to work on setting up the containments of the affected areas. Cavins Group crew members began to HEPA Vac the third floor, followed by a thorough wipe-down using an antimicrobial solution of all areas. Fogging of the entire building with an antimicrobial solution was performed in the morning, the afternoon, and the evening for a total of three times. Temperature and humidity readings were taken on all three levels in the main area and outside.

11/19/23 - Daily Synopsis

Cavins Group arrived on site, once on site all crew members suited up in proper PPE before entering the building. Upon entering the building, air scrubber filters were changed. A complete fogging of the building with an antimicrobial solution was performed, as well as the afternoon and evening, for a total of three times. Temperature and humidity readings were taken on all three levels in the main area and a reading outside. Cavins Group continued setting containment in all areas today. Cavins Group began to HEPA Vac the second floor, followed by a thorough wipe down. After the second floor was finished with the decontamination process, Cavins Group began to HEPA Vac the first floor, followed by a thorough wipe down with an antimicrobial solution in all areas. Cavins Group finished the decontamination process around 1:30 AM and will be back on site tomorrow to change filters, fog the building, and check all equipment.

First Floor - Main Area


Overview Photos: First Floor - Main Area




Room Notes: First Floor - Main Area

First Floor Main Area: 11/16/23 - Equipment On-site

5 - Air Scrubbers



First Floor - Main Area: 11/16/23 - Fogging



First Floor - Main Area: 11/17/23 - Equipment On-site



6 - Air Scrubbers

One additional air scrubber was added to the area today.



First Floor - Main Area: 11/17/23 - Filter Change





First Floor - Main Area: 11/18/23 - Fogging






First Floor - Main Area 11/18/23 - Equipment On-site

6 - Air Scrubbers



First Floor - Main Area: 11/18/23 - Filter Change



First Floor - Main Area: 11/19/23 - Fogging




First Floor - Main Area: 11/19/23 - Equipment On-site

6 - Air Scrubbers





First Floor - Main Area 11/19/23 - Filter Change









First Floor - Main Area: 11/17/23 - Fogging



First Floor - Main Area: 11/19/23 - HEPA Vac










First Floor - Main Area: 11/19/23 - Hepa Vac Bag Change



First Floor - Main Area: 11/19/23 - Wipe Down









First Floor - Main Area: 11/19/23 - Visible Water Intrusion

Visible water intrusion is present on the west side windows.



First Floor - Main Area: 11/19/23 - Final Fogging





First Floor - Main Area: 11/19/23 - Visible Water Intrusion

Visible water intrusion is present on the east entrance windows.



First Floor - Main Area: 11/22/23 - Equipment On-site



1 - air scrubber

First Floor - Main Area: 11/22/23 Filter Change



First Floor - Main Area: 11/23/23 Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air Scrubber

First Floor - Main Area: 11/24/23 Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air Scrubber

Garage

Overview Photos: Garage



Photo 1


Room Notes: Garage

Garage: 11/16/23 - Area Setup



Area prior to the decontamination chamber being built.

Garage: 11/16/23 - Decontamination Chamber Setup



Garage: 11/16/23 - Decontamination Chamber

Decontamination chamber setup completed.



Garage: 11/16/23 - Equipment On-site

- 3 - Air Scrubbers
- 1 - 100' Extension Cord






Garage: 11/16/23 - Fogging

Cavins Group fogged the affected area.




Garage: 11/17/23 - Containment Upon Arrival/Departure



Garage: 11/17/23 - Equipment On-site

3 - Air Scrubbers

1 - 100' Extension Cord



Garage: 11/18/23 - Equipment On-site

3 - Air Scrubbers

1 - 100' Extension Cord






Garage: 11/19/23 - Containment Upon Arrival/Departure



Garage: 11/18/23 - Containment Upon Arrival/Departure



Garage: 11/19/23 - Equipment On-site

3 - Air Scrubbers
100' extension cord



Garage: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 3 - Air Scrubbers
- 100' extension cord

Garage: 11/24/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 3 - Air Scrubbers
- 100' extension cord

115 - Staff Only


Overview Photos: 115 - Staff Only




Room Notes: 115 - Staff Only


SO 115: 11/16/23 - Plants

Plant location prior to containment setup. This is used as a reference for post-remediation build-back plant placement.







SO 115: 11/16/23 - Prior to Containment



Area view prior to containment set up




SO 115: 11/16/23 - Containment Setup Process







SO 115: 11/16/23 - Containment




Containment setup completed





SO 115: 11/16/23 - Equipment On-site

2 - Air Scrubbers





SO 115: 11/16/23 - Fogging







SO 115: 11/17/23 - Containment Upon Arrival/Departure













SO 115: 11/17/23 - Equipment On-site






2 - Air Scrubbers




SO 115: 11/17/23 - Fogging










SO 115: 11/19/23 - Containment Upon Arrival/Departure





SO 115: 11/18/23 - Containment Upon Arrival/Departure







SO 115: 11/18/23 - Equipment On-site


2 - Air Scrubbers



SO 115: 11/18/23 - Fogging





SO 115: 11/19/23 - Fogging



SO 115: 11/19/23 - Equipment On-site

2 - Air Scrubbers



SO 115: 11/23/23 - Equipment on Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

2 - Air Scrubbers

SO 115: 11/24/23 - Equipment on Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

2 - Air Scrubbers

Contents - Room 115 - Staff Only

Overview Photos: Contents - Room 115 - Staff Only



Contents - Storage Room: 137

Overview Photos: Contents - Storage Room: 137






Room Notes: Contents - Storage Room: 137





Room: 137 - Content Cleaning/Decontamination: 11/29/23

Cavins Group cleaned/decontaminated 44 plastic tubs per The City of Normans request. Contents were Hepa Vacuumed, and cleaned with an antimicrobial solution. Once cleaning/decontamination was finished all items were marked with an orange sticker with a "D" on them. When decontamination was completed, all contents were delivered to the west side library per The City of Normans request.




Contents: Contents - Storage Room: 137











First Floor - Southwest Vestibule

Overview Photos: First Floor - Southwest Vestibule



Room Notes: First Floor - Southwest Vestibule

First Floor - Southwest Vestibule: 11/17/23 - Pre Containment



First Floor - Southwest Vestibule: 11/17/23 - Post Containment



First Floor - Southwest Vestibule: 11/17/23 - Containment Process




First Floor - Southwest Vestibule: 11/17/23 - Equipment On-site



2 - Air Scrubbers

First Floor - Southwest Vestibule: 11/18/23 - Containment Upon Arrival



First Floor - Southwest Vestibule: 11/18/23 - Equipment On-site



2 - Air Scrubbers

First Floor - Southwest Vestibule: 11/19/23 - Containment Upon Departure





First Floor - Southwest Vestibule: 11/19/23 - Equipment On-site




2 - Air Scrubbers

First Floor - Southwest Vestibule: 11/19/23 - Containment Upon Arrival

Containment set up is still in progress
Above ceiling work is still being performed





First Floor - Southwest Vestibule: 11/18/23 - Containment Upon Departure



First Floor - Southwest Vestibule: 11/18/23 - Additional Microbial Growth


Due to additional microbial growth found, the containment area was extended.





First Floor - Southwest Vestibule: 11/22/23 - Equipment On-site

- 2 - Air Scrubbers
- 2 - Zip Posts
- 1 - ULV Fogger



First Floor - Southwest Vestibule: 11/22/23 Filter Change and Fogging

- 2 - Air Scrubbers
- 2 - Zip Posts

1 - ULV Fogger



First Floor - Southwest Vestibule: 11/23/23 - Equipment On-Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Air Scrubbers
- 2 - Zip Posts
- 1 - ULV Fogger

First Floor - Southwest Vestibule: 11/24/23 - Equipment On-Site


Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Air Scrubbers
- 2 - Zip Posts
- 1 - ULV Fogger

149 - Storytime

Overview Photos: 149 - Storytime



Room Notes: 149 - Storytime

149: 11/16/23 - Area Overview



Area overview prior to containment setup

149: 11/16/23 - Containment Setup



149: 11/16/23 - Containment



Containment setup in progress

149: 11/16/23 - Equipment On-site

- 2 - Air Scrubbers
- 5 - Zip Post






149: 11/17/23 - Containment Upon Arrival/Departure



149: 11/17/23 - Equipment On-site

- 2 - Air Scrubbers
- 5 - Zip Posts



149: 11/18/23 - Equipment On-site

- 2 - Air Scrubbers
- 5 - Zip Posts



149: 11/18/23 - Containment Upon Arrival/Departure



149: 11/18/23 - Filter Change



149: 11/19/23 - Equipment On-site

- 5 - Zip posts
- 2 - Air scrubbers





149: 11/19/23 - Containment Upon Arrival/Departure





149: 11/19/23 - Filter Change



149: 11/17/23 - Filter Change



149: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 5 - Zip posts
- 2 - Air scrubbers

149: 11/24/23 - Equipment On-site


Cavins Group was closed for Thanksgiving

Equipment on-site:

- 5 - Zip posts
- 2 - Air scrubbers

First Floor - Bay Windows (Children's Area)

Overview Photos: First Floor - Bay Windows (Children's Area)



Room Notes: First Floor - Bay Windows (Children's Area)

Bay Windows (Children's Area): 11/16/23 - Area Overview




Area prior to containment setup

Bay Windows (Children's Area): 11/16/23 - Containment Setup





Bay Windows (Children's Area): 11/16/23 - Containment



Bay Windows (Children's Area): 11/16/23 - Equipment on Site

- 3 - Air Scrubbers
- 12 - Zip Post













Bay Windows (Children's Area): 11/17/23 - Containment Upon Arrival/Departure




Bay Windows (Children's Area): 11/17/23 - Equipment

3 - Air Scrubbers
12 - Zip Posts








**Bay Windows (Children's Area):
11/18/23 - Containment Upon Arrival/Departure**







**Bay Windows (Children's Area):
11/18/23 - Equipment**

3 - Air Scrubbers
12 - Zip Posts







**Bay Windows (Children's Area):
11/18/23 - Filter Changes**




**Bay Windows (Children's Area):
11/19/23 - Fogging**






**Bay Windows (Children's Area):
11/19/23 - Containment Upon Arrival/Departure**






**Bay Windows (Children's Area):
11/19/23 - Filter Change**









**Bay Windows (Children's Area):
11/19/23 - Equipment on Site**

- 12 - Zip Post
- 3 - Air Scrubbers





Bay Windows (Children's Area): 11/17/23 - Filter Change



Bay Windows (Children's Area): 11/23/23 - Equipment on Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 12 - Zip Post
- 3 - Air Scrubbers

Bay Windows (Children's Area): 11/24/23 - Equipment on Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 12 - Zip Post
- 3 - Air Scrubbers

Second Floor - Main Area


Overview Photos: Second Floor - Main Area




Room Notes: Second Floor - Main Area

Second Floor - Main Area: 11/16/23 - Equipment On-site




3 - Air Scrubbers



Second Floor - Main Area: 11/16/23 - Fogging



Second Floor - Main Area: 11/17/23 - Fogging




Second Floor - Main Area: 11/17/23 - Filter Change




Second Floor - Main Area: 11/17/23 - Equipment On-site

3 - Air Scrubbers



Second Floor - Main Area: 11/18/23 - Filter Change








Second Floor - Main Area: 11/18/23 - Equipment On-site

3 - Air Scrubbers



Second Floor - Main Area: 11/19/23 - Fogging










Second Floor - Main Area: 11/19/23 - Equipment On-site

3 - Air Scrubbers




Second Floor - Main Area: 11/19/23 - HEPA Vac










Second Floor - Main Area: 11/19/23 - Filter Change




Second Floor - Main Area: 11/18/23 - Fogging







Second Floor - Main Area: 11/19/23 - Wipe Down





Second Floor - Main Area: 11/19/23 - Final Fogging





Second Floor - Main Area: 11/19/23 - Hepa Vac Bag Change




Second Floor - Main Area: 11/22/23 - Equipment On-site



1 air scrubber

Second Floor - Main Area: 11/22/23 - Filter Change



Second Floor - Main Area: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 air scrubber

Second Floor - Main Area: 11/24/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 air scrubber

201A - Staff Only

Overview Photos: 201A - Staff Only





Room Notes: 201A - Staff Only

201A: 11/16/23 - Area Setup



Area setup prior to containment

201A: 11/16/23 - Containment Setup







201A: 11/16/23 - Containment




Containment setup in progress


201A: 11/16/23 - Equipment On-site

- 2 - Air Scrubbers
- 7 - Zip Post






201A: 11/16/23 - Fogging



201A: 11/17/23 - Containment Upon Arrival/Departure




201A: 11/17/23 - Equipment On-site

- 2 - Air Scrubbers
- 7 - Zip Posts






201A: 11/17/23 - HEPA Vac









201A: 11/18/23 - Fogging



201A: 11/17/23 - Fogging




201A: 11/18/23 - Filter Change



201A: 11/18/23 - Equipment On-site

- 2 - Air Scrubbers
- 7 - Zip Posts









201A: 11/18/23 - Containment Upon Arrival/Departure



201A: 11/19/23 - Containment Upon Arrival/Departure




201A: 11/19/23 - Hepa Vac








201A: 11/19/23 - Equipment On-site

- 2 - Air Scrubbers
- 7 - Zip Post






201A: 11/19/23 - Filter Change



201A: 11/17/23 - Filter Change



201A: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Air Scrubbers
- 7 - Zip Post

201A: 11/24/23 - Equipment On-site


Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Air Scrubbers
- 7 - Zip Post


Second Floor - Bathroom

Overview Photos: Second Floor - Bathroom





Room Notes: Second Floor - Bathroom

Second Floor Bathroom: 11/16/23 Overall Area



Overall area prior to containment setup

Second Floor Bathroom: 11/16/23 - Containment Setup




Second Floor Bathroom: 11/16/23 Containment



Containment setup complete

Second Floor Bathroom: 11/16/23 - Equipment On-site

- 1 - Air Scrubber
- 4 - Zip Post






Second Floor Bathroom: 11/17/23 - Fogging






Second Floor Bathroom: 11/17/23 - Containment Upon Arrival/Departure





Second Floor Bathroom: 11/17/23 - Equipment On-site

- 1 - Air Scrubber
- 4 - Zip Posts



Second Floor Bathroom: 11/16/23 - Fogging




Second Floor Bathroom: 11/18/23 - Containment Upon Arrival/Departure



Second Floor Bathroom: 11/18/23 - Equipment On-site

- 1 - Air Scrubber
- 2 - Zip Posts



Second Floor Bathroom: 11/19/23 - Containment Upon Arrival and Departure



Second Floor Bathroom: 11/19/23 - Equipment On-site

- 2 - Zip Post
- 1 - Air Scrubber



Second Floor Bathroom: 11/18/23 - Fogging



Second Floor Bathroom: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Zip Post
- 1 - Air Scrubber

Second Floor Bathroom: 11/24/23 - Equipment On-site


Cavins Group was closed for Thanksgiving

Equipment on-site:

- 2 - Zip Post

Second Floor - Southeast Corner


Overview Photos: Second Floor - Southeast Corner



Room Notes: Second Floor - Southeast Corner



Second Floor - SE Corner: 11/16/23 - Area Overall Setup

Area prior to containment being set up






Second Floor - SE Corner: 11/16/23 - Containment

Containment setup completed



Second Floor - SE Corner: 11/16/23 - Containment Setup







Second Floor - Southeast Corner: 11/16/23 - Equipment On-site

- 20 - Zip Post
- 4 - Air Scrubbers








Second Floor - SE Corner: 11/16/23 - Additional Microbial Growth

Due to additional microbial growth found, the containment area had to be expanded to contain the affected areas.






Second Floor - SE Corner: 11/16/23 - Fogging



Second Floor - SE Corner: 11/17/23 - Equipment On-site

- 20 - Zip Posts
- 4 - Air Scrubbers












Second Floor - SE Corner: 11/17/23 - Containment Upon Arrival/Departure



Second Floor - SE Corner: 11/17/23 - Containment Upon Arrival/Departure



Second Floor - Southeast Corner: 11/17/23 - Fogging



Second Floor - SE Corner: 11/17/23 - HEPA Vac








Second Floor - Southeast Corner: 11/18/23 - Equipment On-site

20 - Zip Post
4 - Air Scrubbers








Second Floor - Southeast Corner: 11/18/23 - Containment Upon Arrival/Departure







Second Floor - Southeast Corner: 11/19/23 - Containment Upon Arrival/Departure



Second Floor - Southeast Corner: 11/19/23 - Equipment On-site


- 20 - Zip Post
- 4 - Air Scrubbers








Second Floor - Southeast Corner: 11/19/23 - Filter Change




Second Floor - Southeast Corner: 11/17/23 - Filter Change








Second Floor - Southeast Corner: 11/18/23 - Filter Change





Second Floor - Southeast Corner: 11/22/23 - Equipment On-site






- 20 - Zip Post
- 4 - Air Scrubbers







Second Floor - Southeast Corner: 11/22/23 Filter Change and Fogging



Second Floor - Southeast Corner: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

20 - Zip Post

4 - Air Scrubbers

Second Floor - Southeast Corner: 11/24/23 - Equipment On-site

Cavins Group was closed for Thanksgiving


Equipment on-site:

20 - Zip Post

4 - Air Scrubbers

Second Floor - South Windows

Overview Photos: Second Floor - South Windows



Room Notes: Second Floor - South Windows

Second Floor - South Windows: 11/16/23



Area prior to containment setup

Second Floor - South Windows: 11/16/23 - Containment



Containment setup

Third Floor - Main Area

Overview Photos: Third Floor - Main Area




Photo 1

Room Notes: Third Floor - Main Area

Third Floor - Common Area: 11/16/23 - Equipment On-site

4 - Air Scrubbers






Third Floor - Common Area: 11/16/23 - Fogging





Third Floor - Common Area: 11/17/23 - Fogging






Third Floor - Common Area: 11/17/23 - Equipment On-site

4 - Air Scrubbers




Third Floor - Common Area: 11/17/23 - HEPA Vac









Third Floor - Common Area: 11/17/23 - Filter Change








Third Floor - Common Area: 11/18/23 - Wipe Down




Third Floor - Common Area: 11/17/23 - Fogging






Third Floor - Common Area: 11/18/23 - Filter Change



Third Floor - Common Area: 11/18/23 - HEPA Vac





Third Floor - Common Area: 11/18/23 - Equipment On-site

4 - Air Scrubbers






Third Floor - Common Area: 11/19/23 - Fogging




Third Floor - Common Area: 11/19/23 - Wipe Down




Third Floor - Common Area: 11/19/23 - Equipment On-site

4 - Air Scrubbers



Third Floor - Common Area: 11/19/23 - Filter Change








Third Floor - Common Area: 11/18/23 - Fogging



Third Floor - Main Area: 11/19/23 - Final Fogging



Third Floor - Main Area: 11/18/23 - Hepa Vac Bag Change



Third Floor - Main Area: 11/22/23 - Equipment On-site



1 - Air Scrubber

**Third Floor - Main Area:
11/22/23 - Filter Change**



Third Floor - Main Area: 11/22/23 Interior Temperature and Humidity



25% humidity
70F. Temperature

Third Floor - Main Area: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air Scrubber

Third Floor - Main Area: 11/24/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air Scrubber


305 - Pioneer Room

Overview Photos: 305 - Pioneer Room



Room Notes: 305 - Pioneer Room

305: 11/16/23: Area prior to containment set up



305: 11/16/23 - Containment







305: 11/16/23 - Containment Setup



305: 11/16/23 - Equipment On-site

- 2 - Air Scrubbers
- 4 - Zip Post









305: 11/16/23 - Fogging




305: 11/17/23 - HEPA Vac



305: 11/17/23 - Containment Upon Arrival/Departure






305: 11/17/23 - Fogging



305: 11/17/23 - Equipment On-site

- 2 - Air Scrubbers
- 4 - Zip Post





305: 11/18/23 - Filter Change



305: 11/18/23 - Equipment On-site

- 2 - Air Scrubbers
- 4 - Zip Post







305: 11/18/23 - Containment Arrival Upon Departure





305: 11/18/23 - Fogging



305: 11/18/23 - HEPA Vac



305: 11/19/23 - Containment Upon Arrival and Departure




305: 11/19/23 - Equipment On-site

- 2 - Air Scrubbers
- 4 - Zip Post





305: 11/17/23 - Filter Change




305: 11/22/23 - Equipment On-site


- 4 - Zip post
- 2 - Air scrubbers
- 1 - Fogger





305: 11/22/23 - Filter Change and Fogging






305: 11/29/23 Equipment On-site

4 Zip Post
2 Air Scrubbers





305: 11/29/23 Filter Change



305: 11/23/23 Equipment On-Site

Cavins Group was closed for Thanksgiving

Equipment on-site:

- 4 Zip Post
- 2 Air Scrubbers

305: 11/24/23 Equipment On-Site

Cavins Group was closed for Thanksgiving


Equipment on-site:

4 Zip Post

2 Air Scrubbers


Southwest Stairwell

Overview Photos: Southwest Stairwell



Room Notes: Southwest Stairwell

SW Stairwell: 11/16/23:
Prior to containment setup



SW Stairwell: 11/16/23 - Containment Setup




SW Stairwell: 11/16/23 Equipment On-site



1 airscrubber

SW Stairwell: 11/16/23 - Containment



Containment setup completed

SW Stairwell: 11/17/23 - Equipment On-site



1 - Air Scrubber


SW Stairwell: 11/19/23 - Containment Upon Arrival/Departure



SW Stairwell: 11/17/23 - Containment Upon Departure



SW Stairwell: 11/18/23 Filter Change



SW Stairwell: 11/18/23 - Containment Upon Arrival/Departure



SW Stairwell: 11/18/23 - Equipment On-site




1 - Air Scrubber

SW Stairwell: 11/19/23 - Equipment On-site




1 - Air Scrubber

SW Stairwell: 11/22/23 - Equipment On-site



1 - Air scrubber

SW Stairwell: 11/22/23 - Filter Change and Fogging





SW Stairwell: 11/23/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air scrubber

SW Stairwell: 11/24/23 - Equipment On-site

Cavins Group was closed for Thanksgiving

Equipment on-site:

1 - Air scrubber