

Date Wed 11/29/2023

Job #

Weather

6:00 AM

36° 

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 71%

12:00 PM

60° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 44%

4:00 PM

63° 

Clear

Wind: 16 MPH | Precipitation: .0" | Humidity: 37%

Work Logs

Name	Description
Cavins Environmental	<p>Cavins Group inspected containments for defects, all equipment was checked, and all filters were changed. Temperature and humidity readings were taken on all three main levels, and one exterior reading was taken. Contents were cleaned/decontaminated and removed from the premises per a retrieval list given by the City of Norman.</p> <p>Cavins environmental testing technician took four samples in common areas and one exterior control sample. This testing is performed weekly to monitor the air quality in the common areas.</p>
Total	


General Notes

1. Weekly Common Area Testing

Spore trap samples were taken in common areas on each floor, the children's areas, and an exterior control sample. This weekly testing is to monitor the air quality in the common areas.



3rd floor



3rd floor




3rd floor



2nd floor



2nd floor



2nd floor



2nd floor



1st floor



1st floor




1st floor



Childrens area



Childrens area




Childrens area




Childrens Area



2. Pioneer 305: Filter Change



3. Pioneer 305: Equipment On-site
4 Zip Post
2 Air Scrubbers





4. 311 Local History: Equipment On-site

2 - Air Scrubbers





5. 311 Local History: Filter Change




6. Storage Room 137: Content Cleaning/Decontamination

Cavins Group cleaned/decontaminated 44 plastic tubs from Storage Room 137. Items were not in a contaminated area.





7. Third Floor - Main Area: Equipment On-site
1 - Air Scrubber
1 - 25' Extension Cord



8. Third Floor - Main Area: Temperature/Humidity Reading



9. Second Floor - 201A: Equipment On-site
7 Zip Post
2 Air Scrubbers





10. Second Floor - 201A: Filter Change



11. Second Floor - Main Area: Temperature/Humidity Reading



12. Storage Room 137: Overall Photo Pre Content Cleaning/Decontamination



13. Exterior: Temperature and Humidity



**14. Exterior: Equipment On-site
2 - 20' Conex**



15. Storage Room 137: Overall Content Cleaning/Decontamination

Cavins Group cleaned/decontaminated 44 plastic tubs.



16. Second Floor - Southeast Corner: Filter Change



17. Third Floor - Main Area: Filter Change



18. Second Floor - Main Area: Filter Change











19. Second Floor - Main Area: Equipment On-site
1 - Air Scrubber
1 - 25' Extension Cord





20. Second Floor - Southeast Corner: Equipment On-site

6 - Air Scrubbers
22 - Zip Posts








21. SW Stairwell: Equipment On-site
1 Air Scrubber



22. SW Stairwell: Filter Change



23. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



24. 305 Pioneer: Containment Upon Arrival/Departure



25. 311 Local History: Containment Upon Arrival/Departure



26. Second Floor - 201a: Containment Upon Arrival/Departure



**27. First Floor - Main Area: Equipment On-site
2 - Air Scrubbers**




28. First Floor - Main Area: Filter Change



29. First Floor - Southwest Vestibule: Filter Change



30. First Floor - Southwest Vestibule: Equipment On-site
4 - Air Scrubbers
6 - Zip Posts





31. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



32. First Floor - 149: Containment Upon Arrival/Departure



33. 149 Storytime: Equipment On-site
2 - Air Scrubbers
5 - Zip Posts








34. First Floor -149 Storytime: Filter Change



35. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure:




36. First Floor - Bay Windows (Children's Area): Equipment On-site
3 - Air Scrubbers
12 - Zip Posts
1 - 25' Extension Cord






37. First Floor - Bay Windows (Children's Area): Filter Change



38. SO 115: Equipment On-site

2 - Air Scrubbers




39. SO 115: Containment Upon Arrival/Departure



40. SO 115: Filter Change




41. Garage: Equipment On-site
5 - Air Scrubbers
2 - 50' Extension Cord



42. Garage: Filter Change





43. Storage Room 137: Prior to Content Cleaning/Decontamination



44. Overall Equipment On-site:

- 33 - Air Scrubbers
- 56 - Zip Posts
- 3 - 25' Extension Cords
- 2 - 50' Extension Cords
- 2 - 20' Conex Boxes