

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Fri 12/01/2023

Job #

Weather

6:00 AM

42°

Overcast

Wind: 15 MPH | Precipitation: .0" | Humidity: 91%

12:00 PM

40°

Overcast

Wind: 11 MPH | Precipitation: .0" | Humidity: 86%

4:00 PM

40°

Overcast

Wind: 6 MPH | Precipitation: .0" | Humidity: 82%


Work Logs

Name	Description
Cavins Environmental	Cavins Group inspected all equipment and containments, followed by changing of all air filter scrubbers. Humidity and temperature readings were checked on all three floors in the main area, as well as one exterior reading. Cavins technician removed artwork from the second floor main area. All items were delivered to the west side library, per The City of Normans request. Cavins technician removed requested items from Storage Room:137, and began the cleaning/decontamination process.
Total	

General Notes

1. 305 - Pioneer: Filter Change







2. Third Floor - Main Area: Temperature and Humidity



3. 305 - Pioneer: Containment Upon Arrival/Departure



4. 305 - Pioneer: Equipment On-site
4 - Zip Posts
2 - Air Scrubbers






5. 311 - Local History: Containment Upon Arrival/Departure





6. 311 - Local History: Equipment On-site

2 - Air Scrubbers



7. 311 - Local History: Filter Change





8. Third Floor - Main Area - Equipment On-site


1 - Air Scrubber



9. Third Floor - Main Area: Filter Change



10. Second Floor - Main Area: Filter Change



11. Second Floor - Main Area: Temperature and Humidity





12. Second Floor - Southeast Corner: Filter Change








13. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




14. Second Floor - Southeast Corner: Equipment On-site

- 22 - Zip Posts
- 6 - Air Scrubbers







15. SW Stairwell: Filter Change




16. SW Stairwell: Equipment On-site

1 - Air Scrubber





17. SO 201A: Containment Upon Arrival/Departure



18. SO 201A: Equipment On-site

- 7 - Zip Posts
- 2 - Air Scrubbers



19. SO 201A: Filter Change




20. First Floor - 149 Storytime: Containment Upon Arrival/Departure




21. First Floor - 149 Storytime: Equipment On-site

- 2 - Air Scrubbers
- 5 - Zip Posts




22. First Floor - 149 Storytime: Filter Change



23. Exterior: Equipment On-site
2 - 20' Conex



24. Exterior: Temperature and Humidity




25. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




26. First Floor - Bay Windows (Children's Area): Equipment On-site

- 12 - Zip Posts
- 3 - Air Scrubbers
- 1 - 25' Extension Cord



27. First Floor - Bay Windows (Children's Area): Filter Change



28. First Floor - Main Area: Filter Change




29. First Floor - Southwest Vestibule - Containment Upon Arrival/Departure



30. First Floor - Southwest Vestibule: Equipment On-site
 2 - Air Scrubbers
 2 - Zip Posts



31. First Floor - Southwest Vestibule: Filter Change



32. First Floor - Main Area: Equipment On-site
 2 - Air Scrubbers





33. First Floor - Main Area: Temperature and Humidity





34. SO 115: Equipment On-site

3 - Air Scrubbers





35. SO 115: Filter Change








36. Garage: Equipment On-site

- 4- Air Scrubbers
- 2 - 50' Extension Cords
- 3 - 25' Extension Cords





37. Garage: Filter Change




38. Overall Equipment On-site:

- 31 - Air Scrubbers
- 52 - Zip Posts
- 2 - 20' Conex
- 4 - 25' Extension Cords
- 2 - 50' Extension Cords

39. Storage Room 137: Cleaning/Decontamination/Delivery

Cavins Group technician HEPA vacuumed items in a contaminated area, followed by an antimicrobial wipe-down as a precautionary measure. At the request of the City of Norman Pioneer Library staff, all items were delivered to the west side library.



40. Second Floor - Main Area: Equipment On-site

1 - Air Scrubber

