

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sat 12/09/2023

Job #

Weather

6:00 AM

42° 

Clear

Wind: 11 MPH | Precipitation: .0" | Humidity: 76%

12:00 PM

49° 

Partially cloudy

Wind: 18 MPH | Precipitation: .0" | Humidity: 45%

4:00 PM

50° 

Clear



Wind: 22 MPH | Precipitation: .0" | Humidity: 36%

Work Logs

Name	Description
Cavins Environmental	Cavins Group arrived on site and suited up in appropriate PPE. Upon suiting up all containments and equipment were checked for defects. Filters were changed in all air scrubbers. Temperature and humidity readings were taken in all containment areas, common areas, and outside. Room 305 was fogged with an antimicrobial and is still in the air scrubbing process. 305 will be ready for post remediation verification on Tuesday, December 12, 2023.
Total	


General Notes

1. 201A Staff Only: Containment Upon Arrival/Departure






2. 201A Staff Only: Equipment

- 10 - Zip Posts
- 3 - Air Scrubbers
- 1 - Fogger



3. 201A Staff Only: Filter Changes






4. 201A Staff Only: Temperature and Humidity



5. 303 Storage: Containment Upon Arrival/Departure




6. 303 Storage: Equipment

- 1 - Air Scrubbers
- 2 - Zip post
- 1 - Fogger




7. 303 Storage: Filter Changes




8. 115 Staff Only: Containment Upon Arrival/Departure



9. 115 Staff Only: Equipment On-site
6 - Air Scrubbers
1 - Fogger



10. 115 Staff Only: Filter Changes



11. 115 Staff Only: Temperature And Humidity






12. 149 Story Time: Containment upon Arrival/Departure



13. 303 Storage: Temperature and Humidity





14. 305 Pioneer: Containment upon Arrival/Departure







15. 305 Pioneer: Equipment

- 2 - Air Scrubbers
- 4 - Zip post
- 1 - Fogger



16. 305 Pioneer: Filter Changes




17. 305 Pioneer: Temperature and Humidity




18. 311 Local History: Containment Upon Arrival/Departure



19. 311 Local History: Equipment
2 - Air Scrubbers
1 - Fogger



20. 311 Local History: Filter Changes







21. 311 Local History: Temperature and Humidity



**22. Exterior: Equipment
2 - Conex**



23. Exterior: Temperature and Humidity




24. First Floor - Bay Windows Children's Area: Containment Upon Arrival/Departure




25. First Floor - Bay Windows Children's Area: Equipment.

- 3 - Air Scrubbers
- 12 - Zip Post
- 1 - Fogger
- 1 - 50' Extension Cord





26. First Floor - Bay Windows Children's Area: Filter Changes





27. First Floor - Bay Windows Children's Area: Temperature And Humidity



28. First Floor - Main Area: Equipment
2 - Large Air Scrubbers




29. First Floor - Main Area: Filter Changes



30. First Floor - Main Area: Temperature and Humidity



31. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




32. First Floor - Southwest Vestibule: Equipment.

- 2 - Medium Air Scrubbers
- 2 - Zip Post
- 1 - Fogger



33. First Floor - Southwest Vestibule: Filter Changes




34. First Floor - Southwest Vestibule: Temperature And Humidity



35. Garage: Containment Upon Arrival/Departure




- 36. Garage: Equipment.**
- 1 - Large Air Scrubber
 - 3 - Medium Air Scrubbers
 - 1 - 25' Extension Cord
 - 2 - 50' Extension Cords
 - 2 - Foggers




37. Garage: Filter Changes





38. Garage: Temperature And Humidity



39. Overall Equipment Onsite:

- 57 - Zip Posts
- 38 - Air Scrubbers
- 2 - 25' Extension Cords
- 2 - Conex Boxes
- 3 - 50' Extension Cords
- 2 - 100' Extension Cords

40. Second Floor - Main Area: Equipment

- 1 - Large Air Scrubber
- 1 - 25' Extension Cord







41. Second Floor - Main Area: Filter Changes



42. Second Floor - Main Area: Temperature And Humidity




43. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




44. Second Floor - Southeast Corner: Equipment.


- 22 - Zip post
- 6 - Medium Air Scrubbers
- 1 - 50' Extension cord
- 1 - Fogger





45. Second Floor - Southeast Corner: Filter Changes







46. Stairwell - Containment Upon Arrival/Departure



47. Stairwell - Equipment On Site
 3 air scrubber
 2 100' extension cords



48. Stairwell - Filter Changes



49. Stairwell - Humidity and Temperature



50. Third Floor - Main Area: Equipment
1 Large Air Scrubber
1 50' Extension Cord




51. Third Floor - Main Area: Filter Change



52. Third Floor - Main Area: Temperature and Humidity



53. 303 Storage: Antimicrobial Fog Treatment



54. 305 Pioneer: Antimicrobial Fog Treatment



55. Second Floor - Southeast Corner: Temperature and Humidity







56. 149 Story Time: Equipment

- 2 - Air Scrubbers
- 1 - Fogger
- 5- Zip Posts





57. 149 Story Time: Filter Changes



58. 149 Story Time: Temperature and Humidity

