

Date Sun 12/10/2023

Job #

## Weather

6:00 AM

28° 

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 59%

12:00 PM

46° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 27%

4:00 PM

51° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 22%

## Work Logs

Name	Description
Cavins Environmental	Cavins Group arrived on site and suited up in appropriate PPE. Upon suiting up all containments and equipment were checked for defects. Filters were changed in all air scrubbers. Temperature and humidity readings were taken in all containment areas, common areas, and outside. Room 305 was fogged with an antimicrobial and is still in the air scrubbing process. 305 will be ready for post remediation verification on Tuesday, December 12, 2023.
Total	


## General Notes

### 1. SO 115: Containment Upon Arrival/Departure







### 2. SO 115: Equipment On- Site

- 1 - Large Air Scrubber
- 5 - Medium Air Scrubbers
- 1 - Fogger



### 3. SO 115: Filter Changes






**4. SO 115: Temperature And Humidity**




**5. 149 Storytime: Equipment On-Site**

- 5 - Zip Posts
- 2 - Medium Air Scrubbers
- 1 - Fogger











6. 149 Storytime: Containment Upon Arrival/Departure



7. 149 Storytime: Filter Changes



8. 149 Storytime: Temperature And Humidity




**9. First Floor - Southwest Vestibule: Equipment On-Site**

- 2 - Medium Air Scrubbers
- 2 - Zip Posts
- 1 - Fogger



**10. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**



**11. First Floor - Southwest Vestibule: Filter Changes**



**12. First Floor - Southwest Vestibule: Temperature And Humidity**



**13. First Floor - Main Area: Equipment On-Site**

2 - Large Air Scrubbers



**14. First Floor - Main Area: Filter Changes**



15. First Floor - Main Area: Temperature And Humidity



16. Exterior: Equipment On-Site

2 - Conex




17. Exterior: Temperature And Humidity



**18. Third Floor - Main Area: Equipment On-Site**

- 1 - Large Air Scrubber
- 1 - 50' Extension Cord



**19. Third Floor - Main Area: Filter Change**




**20. Third Floor - Main Area: Temperature and Humidity**





**21. 305 Pioneer: Equipment On-Site.**

- 2 - Medium Air Scrubbers
- 4 - Zip Post
- 1 - Fogger





**22. 305 Pioneer: Filter Changes**



**23. 305 Pioneer: Temperature and Humidity**



24. 305 Pioneer: Containment upon Arrival/Departure



25. 311 Local History: Equipment On-Site

- 2 - Medium Air Scrubbers
- 1 - Fogger




26. 311 Local History: Containment Upon Arrival/Departure




27. 303 Storage: Equipment On-Site

- 1 - Medium Air Scrubber
- 2 - Zip Post

### 1 - Fogger



### 28. 311 Local History: Filter Changes



### 29. 311 Local History: Temperature And Humidity



### 30. 303 Storage: Temperature and Humidity




31. 303 Storage: Containment upon Arrival/Departure



32. 305 Pioneer: Anti Microbial Fog Treatment



33. 303 Storage: Filter Changes



34. 303 Storage: Anti Microbial Fog Treatment



**35. Second Floor - Main Area: Equipment On-Site**

- 1 - Large Air Scrubber
- 1 - 25' Extension Cord



**36. Second Floor - Main Area: Filter Changes**




**37. Second Floor - Main Area: Temperature And Humidity**




**38. 201A Staff Only: Equipment On-Site**

- 3 - Medium Air Scrubbers
- 10 - Zip Post
- 1 - Fogger



**39. 201A Staff Only: Containment upon Arrival/Departure**



40. 201A Staff Only: Temperature and Humidity





41. 201A Staff Only: Filter Changes



42. 201A Staff Only: Anti Microbial Fog Treatment



**43. Second Floor - Southeast Corner: Containment Upon Arrival/Departure**



**44. Second Floor - Southeast Corner: Equipment On-Site.**

- 22 - Zip Posts
- 6 - Medium Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension Cord













45. Second Floor - Southeast Corner: Filter Changes





**46. Second Floor - Southeast Corner: Temperature And Humidity**









**47. Stairwell: Equipment On-Site**

- 1 - Medium Air Scrubber
- 2 - Large Air Scrubbers
- 2 - 100' Extension Cords
- 1 - Fogger






**48. Stairwell: Filter Changes**




**49. Stairwell: Temperature and Humidity**



**50. Stairwell: Containment upon Arrival/Departure**



**51. Stairwell: Anti Microbial Fog Treatments**




**52. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure**



**53. First Floor - Bay Windows (Children's Area): Equipment On-Site.**

- 12 - Zip Posts
- 3 - Medium Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension Cord



54. First Floor - Bay Windows (Children's Area): Filter Changes






**55. First Floor - Bay Windows (Children's Area): Temperature And Humidity**






**56. Garage: Equipment On-Site**

- 1 - Large Air Scrubber
- 3 - Medium Air Scrubbers
- 1 - Fogger
- 1 - 25' Extension Cord
- 2 - 50' Extension Cords



57. Garage: Filter Changes








**58. Garage: Containment upon Arrival/Departure**











**59. Garage: Temperature and Humidity**



**60. SO 115: Desk Contents Removal**







**61. Overall: Equipment On-Site.**

- 38 - Air Scrubbers
- 57 - Zip Posts
- 5 - 50' Extension Cords
- 2 - 25' Extension Cords
- 2 - 100' Extension Cords
- 4 - Foggers