

Date Thu 12/14/2023

Job #

Weather

6:00 AM

45° 

Overcast

Wind: 7 MPH | Precipitation: .0" | Humidity: 58%

12:00 PM

56° 

Partially cloudy

Wind: 10 MPH | Precipitation: .0" | Humidity: 38%

4:00 PM

57° 

Overcast

Wind: 10 MPH | Precipitation: .0" | Humidity: 32%

Work Logs

Name	Description
City of Norman Central Library - Mold	<p>Cavins Group arrived on site and suited up in proper PPE. Upon suiting up Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians continued to inventory items in SO 115. All inventoried items have been cleaned/decontaminated, or disposed of per The City of Norman's request. All cleaned/decontaminated items have been stored on site. Cavins technician began to cover furniture in SO 115 with plastic to prepare for remediation.</p> <p>Cavins technician fogged 201A with an antimicrobial solution for a second round of fogging.</p> <p>One window was removed in the Main Entrance Children's Area containment to allow for a fresh air intake to be installed.</p>
Total	


General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Main Entrance - Children's Area: New Containment Upon Departure




3. Main Entrance - Children's Area: Negative Air Installation



**4. 305 Pioneer: Equipment
4 - Zip Post**



5. 305 Pioneer: Containment Upon Arrival/Departure



6. Exterior: Temperature and Humidity




7. Third Floor - Main Area: Temperature and Humidity



8. Third Floor - Main Area: Equipment

- 1 - 50' Extension Cord
- 1 - Air Scrubber



9. 311 Local History: Containment Upon Arrival/Departure






10. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



11. 311 Local History: Filter Change



12. Third Floor - Main Area: Filter Change



13. 311 Local History: Temperature and Humidity



14. 303 Storage: Equipment

2 - Zip Post




15. 303 Storage: Containment Upon Arrival/Departure



16. Second Floor - Main Area: Equipment


2 - Air Scrubbers
1 - 25' Extension Cord



17. Second Floor - Main Area: Temperature and Humidity




18. Second Floor - Main Area: Filter Change



19. SO 115: Content Cleaning/Decontamination/Disposal








20. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



21. Second Floor - Southeast Corner: Equipment






- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord







22. Second Floor - Southeast Corner: Filter Change





23. Second Floor - Southeast Corner: Temperature and Humidity




24. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - 50' Extension Cord
- 1 - Fogger











25. Stairwell: Containment Upon Arrival/Departure



26. Stairwell: Filter Change






27. Stairwell: Temperature and Humidity






28. 201A Staff Only: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger






29. 201A Staff Only: Filter Change



30. 201A Staff Only: Temperature and Humidity



31. 201A Staff Only: Containment Upon Arrival/Departure



32. 149 Storytime: Containment Upon Arrival/ Departure






33. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers





34. 149 Storytime: Filter Change




35. 149 Storytime: Temperature and Humidity



36. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




37. First Floor - Bay Windows (Children's Area): Equipment
 12 - Zip Posts
 4 - Air Scrubbers
 1 - 50' Extension Cord





38. First Floor - Bay Windows (Children's Area): Filter Change



39. First Floor - Bay Windows (Children's Area): Temperature and Humidity



40. First Floor - Main Area: Temperature and Humidity





41. First Floor - Main Area: Equipment

2 - Air Scrubbers




42. First Floor - Main Area: Filter Change







43. Main Entrance - Children's Area: Equipment

- 7 - Zip Post
- 1 - Air Scrubber



44. Main Entrance - Children's Area: Filter Change



45. Main Entrance - Children's Area: Temperature and Humidity



46. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



47. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Post





48. First Floor - Southwest Vestibule: Filter Change



49. First Floor - Southwest Vestibule: Temperature and Humidity




50. SO 115: Containment Upon Arrival/Departure





51. SO 115: Equipment

7 - Air Scrubbers
1 - Fogger



52. SO 115: Filter Change







53. SO 115: Temperature and Humidity




54. Garage: Containment Upon Arrival/ Departure




55. Garage: Filter Change








56. Garage: Temperature and Humidity





57. Garage: Equipment
 4 - Air Scrubbers
 3 - 50' Extension Cords





58. 201A Staff Only: Second Anti Microbial Fog Treatment



59. Overall: Equipment

- 64 - Zip Post
- 40 - Air Scrubbers
- 8 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 5 - Hepa Vacuums
- 6 - Foggers

60. SO 115: Remediation Preparation

