

Date Fri 12/15/2023

Job #

Weather

6:00 AM

46° 

Rain, Overcast

Wind: 6 MPH | Precipitation: .07" | Humidity: 94%

12:00 PM

47° 

Overcast

Wind: 9 MPH | Precipitation: .0" | Humidity: 95%

4:00 PM

48° 

Overcast


Wind: 8 MPH | Precipitation: .0" | Humidity: 93%

Work Logs

Name	Description
Memo	<p>Cavins Group arrived on site and suited up in proper PPE. Upon suiting up Cavins technicians checked all equipment and containments for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all three containments, all three floors in the main area, and outside.</p> <p>Cavins technician continued to inventory contents from room SO 115. All inventoried contents have been cleaned/decontaminated, or disposed per the City of Norman's request. All cleaned/decontaminated items were boxed and stored on site.</p> <p>Clearance testing was performed in 201A. One spore trap sample was taken, along with temperature and humidity readings at the time of testing. One control sample was also taken outside; however, it was raining at the time the spore trap sample was taken which can impact the results. Exterior temperature and humidity readings were taken at the time of testing.</p> <p>Cavins technician continued remediation in the stairwell.</p> <p>Cavins technician installed more plastic on the ceiling in the Main Entrance - Children's Area to prevent cross contamination.</p>
Total	

General Notes

1. 201A: Clearance Testing/Temperature and Humidity



2. Exterior: Air Quality Testing/Temperature and Humidity
Raining at time of testing



3. 311 Local History: Containment Upon Arrival/Departure



4. 311 Local History: Temperature and Humidity



5. 311 Local History: Equipment

2 - Air Scrubbers



6. 311 Local History: Filter Change



7. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




8. Second Floor - Southeast Corner: Temperature and Humidity



9. Second Floor - Southeast Corner: Equipment

- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - Fogger






10. Second Floor - Southeast Corner: Filter Change



11. 201A Staff Only: Containment Upon Arrival/Departure










12. 201A Staff Only: Temperature and Humidity



13. 201A Staff Only: Equipment



- 10 - Zip Post
- 3 - Air Scrubbers





14. 149 Story Time: Equipment

- 2 - Air Scrubbers
- 5 - Zip Post



15. 149 Story Time: Containment Upon Arrival/Departure



16. 149 Story Time: Filter Change



17. 149 Story Time: Temperature and Humidity



18. Third Floor - Main Area: Temperature and Humidity



19. Third Floor - Main Area: Equipment
1 - Air Scrubber
1 - 50' Extension Cord



20. Third Floor - Main Area: Filter Change



21. Second Floor - Main Area: Temperature and Humidity




22. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord




23. Second Floor - Main Area: Filter Change



24. Main Entrance - Children's Area: Equipment
1 - Air Scrubber
7 - Zip Post






25. Main Entrance - Children's Area: Containment Upon Arrival/Departure




26. Stairwell: Remediation






27. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - 50' Extension Cord
- 1 - Hepa Vac









28. Main Entrance - Children's Area: Filter change



29. Main Entrance - Children's Area: Plastic Installation



30. Exterior Equipment


2 - Conex Boxes





31. Exterior: Temperature and Humidity



32. Stairwell - Filter change





33. Stairwell - Temperature and Humidity




34. First Floor - Main Area: Equipment

2 - Air Scrubbers



35. First Floor - Main Area: Filter Change






36. First Floor - Main Area: Temperature and Humidity



37. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure




38. First Floor - Bay Window's (Children's Area): Temperature and Humidity




39. First Floor - Bay Window's (Children's Area): Equipment

- 4 - Air Scrubbers
- 12 - Zip Post
- 1 - 50' Extension Cord



40. First Floor - Bay Window's (Children's Area): Filter Change



41. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



42. First Floor - Southwest Vestibule: Temperature and Humidity



43. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Post



44. First Floor - Southwest Vestibule: Filter Change






45. 115 Staff Only: Containment Upon Arrival/Departure





46. 115 Staff Only: Temperature and Humidity









47. 115 Staff Only: Equipment


- 7 - Air Scrubbers
- 1 - Fogger





48. 115 Staff Only: Filter Change







49. Garage: Containment Upon Arrival/Departure



50. Garage: Equipment


- 4 - Air Scrubbers
- 3 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers



51. Garage: Temperature and Humidity



52. Garage: Filter Change



53. Overall: Equipment

- 64 - Zip Post
- 40 - Air Scrubbers
- 3 - 100' Extension Cords
- 7 - 50' Extension Cords
- 2 - 25' Extension Cords
- 4 - Hepa Vacuums
- 5 - Foggers

54. 305 Pioneer: Containment Upon Arrival/Departure




55. 305 Pioneer: Equipment

4 - Zip Post



56. 303 Storage: Equipment



57. 303 Storage: Containment Upon Arrival/Departure

