

Date Sat 12/16/2023

Job #

Weather

6:00 AM

38° 

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 89%

12:00 PM

48° 

Clear

Wind: 16 MPH | Precipitation: .0" | Humidity: 53%

4:00 PM

53° 

Clear




Wind: 12 MPH | Precipitation: .0" | Humidity: 39%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up Cavins technicians checked all equipment and containments for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and outside. Cavins technician worked on remediation in the Main Entrance to the Children's Area. Cavins technician covered items in SO 115 to prepare for remediation.
Total	

General Notes

1. Main Entrance - Children's Area: Containment Upon Arrival/Departure



2. Exterior: Equipment

2 - 20' Conex Boxes



3. 305 Pioneer: Containment Upon Arrival/Departure




4. 305 Pioneer: Equipment

4 - Zip Post



5. 303 Storage: Containment Upon Arrival/Departure




6. 303 Storage: Equipment

2 - Zip Post



7. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



8. Third Floor - Main Area: Filter Change



9. Third Floor - Main Area: Temperature and Humidity




10. 311 Local History: Containment Upon Arrival/Departure







11. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



12. 311 Local History: Filter Change



13. 311 Local History: Temperature and Humidity





14. Second Floor - Main Area: Equipment


- 2 - Air Scrubbers
- 1 - 25' Extension Cord



15. Second Floor - Main Area: Filter Change



16. Second Floor - Main Area: Temperature and Humidity




17. 201A Staff Only: Containment Upon Arrival/Departure



18. 201A Staff Only: Equipment

10 - Zip Post






19. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



20. Second Floor - Southeast Corner: Equipment


- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Inch Extension Cord







21. Second Floor - Southeast Corner: Filter Change





22. Second Floor - Southeast Corner: Temperature and Humidity



23. Main Entrance - Children's Area: Negative Air Installation








24. First Floor - Main Area: Equipment

2 - Air Scrubbers



25. First Floor - Main Area: Filter Change



26. First Floor - Main Area: Temperature and Humidity



27. Stairwell: Containment Upon Arrival/Departure




28. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - 50' Extension Cord
- 1 - Fogger



29. Stairwell: Filter Change



30. Stairwell: Temperature and Humidity



31. 149 Storytime: Containment Upon Arrival/Departure






32. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



33. 149 Storytime: Filter Change






34. 149 Storytime: Temperature and Humidity







35. Main Entrance - Children's Area: Equipment

- 3 - Air Scrubbers
- 10 - Zip Post





36. Main Entrance - Children's Area: Filter Change






37. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




38. First Floor - Bay Windows (Children's Area): Equipment

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





39. First Floor - Bay Windows (Children's Area): Filter Change



40. First Floor - Bay Windows (Children's Area): Temperature and Humidity



41. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



42. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers




43. First Floor - Southwest Vestibule: Filter Change



44. First Floor - Southwest Vestibule: Temperature and Humidity





45. SO 115: Containment Upon Arrival/Departure
















46. SO 115: Equipment

7 - Air Scrubbers
1 - Fogger



47. SO 115: Filter Change





48. SO 115: Temperature and Humidity






49. Garage: Containment Upon Arrival/Departure








50. Garage: Equipment

- 4 - Air Scrubbers
- 3 - Foggers
- 3 - 50' Extension Cords
- 1 - 25' Extension Cord






51. Garage: Filter Change






52. Garage: Temperature and Humidity




53. Main Entrance - Children's Area: Temperature and Humidity



54. Main Entrance - Children's Area: Remediation





55. Overall: Equipment

- 67 - Zip Post
- 39 - Air Scrubbers
- 7 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 5 - Foggers

56. SO 115: Remediation Preparation

