

Date Mon 12/18/2023

Job #

Weather

6:00 AM

37° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 84%

12:00 PM

51° 

Clear

Wind: 11 MPH | Precipitation: .0" | Humidity: 31%

4:00 PM

53° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 30%

Work Logs

Name	Description
City of Norman Central Library - Mold	<p>Cavins Group arrived on site and suited up in proper PPE. Upon suiting up Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Third floor main area filters were not changed due to 24 x 24 filters being out at all local distributors.</p> <p>Additional containment was set to the deck in SO 115 to avoid cross contamination. Upon containment being set Cavins technicians began to demo the area.</p> <p>Cavins technicians worked on remediation in the Main Entrance - Children's Area.</p>
Total	

General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Exterior: Temperature and Humidity




3. 305 Pioneer: Containment Upon Arrival/Departure




4. 305 Pioneer: Equipment

4 - Zip Post



5. 303 Storage: Containment Upon Arrival/Departure




6. 303 Storage Equipment:

2- Zip Post



7. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 25' Extension cord



8. Third Floor - Main Area: Temperature and Humidity



9. 311 Local History: Containment Upon Arrival/Departure



10. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



11. 311 Local History: Filter Change



12. 311 Local History: Temperature and Humidity




13. 201A Staff Only: Containment Upon Arrival/Departure




14. 201A Staff Only: Equipment

10 - Zip Post



15. Second Floor - Main Area: Equipment

1 - 50' Extension Cord
2 - Air Scrubbers




16. Second Floor - Main Area: Filter Change



17. Second Floor - Main Area: Temperature and Humidity




18. Second Floor - Southeast Corner: Containment Upon Arrival/Departure






19. Second Floor - Southeast Corner: Equipment

- 6 - Air Scrubbers
- 22 - Zip Post
- 1 - 50' Extension Cord
- 1 - Fogger





20. Second Floor - Southeast Corner: Filter Change



21. Second Floor - Southeast Corner: Temperature and Humidity



22. Stairwell: Containment Upon Arrival/Departure




23. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cord
- 1 - 50' Extension Cord
- 1 - Zip Post





24. Stairwell: Filter Change



25. Stairwell: Temperature and Humidity




26. 149 Story Time - Containment Upon Arrival/Departure




27. 149 Story Time: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger



28. 149 Story Time: Filter Change



29. 149 Storytime: Temperature and Humidity





30. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure










31. First Floor - Bay Window's (Children's Area): Equipment

- 1 - 50' Extension Cord
- 4 - Air Scrubbers
- 12 - Zip Post
- 1 - Fogger





32. First Floor - Bay Window's (Children's Area): Filter Change



33. First Floor - Bay Window's (Children's Area): Temperature and Humidity






34. First Floor - Children's Area Entrance: Containment Upon Arrival/Departure






35. First Floor - Children's Area Entrance: Equipment

- 3 - Air Scrubbers
- 10 - Zip Post





36. First Floor - Children's Area Entrance: Filter Change



37. First Floor - Children's Area Entrance: Temperature and Humidity



38. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



39. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Post




40. First Floor - Southwest Vestibule: Filter Change



41. First Floor - Southwest Vestibule: Temperature and Humidity



42. Main Entrance - Children's Area: Remediation







43. First Floor - Main Area: Equipment

2 - Air Scrubbers



44. First Floor - Main area: Filter Change





45. First Floor - Main Area: Temperature and Humidity




46. So 115: Containment Upon Arrival/Departure



47. So 115: Equipment

- 7 - Air Scrubbers
- 1 - Fogger





48. So 115: Filter Change





49. So 115: Temperature and Humidity





50. Garage: Containment Upon Arrival/Departure





51. Garage: Equipment

- 4 - Air Scrubbers
- 3 - 50' Extension Cords
- 1 - 25' Extension Cord
- 3 - Foggers
- 2 - HEPA Vac



52. Garage - Filter Change






53. Garage - Temperature and Humidity



54. 201A Staff Only - Temperature and Humidity



55. So 115: Cross-Contamination Barrier Installation



56. Overall : Equipment

- 68 - Zip Post
- 39 - Air Scrubbers
- 3 - 100' Extension Cords
- 7 - 50' Extension Cords
- 2 - 25' Extension Cords
- 6 - Foggers