

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Fri 12/29/2023

Job #

Weather

6:00 AM

30° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 81%

12:00 PM

45° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 57%

4:00 PM

51° 

Clear

Wind: 13 MPH | Precipitation: .0" | Humidity: 36%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

General Notes

1. 149 Storytime: Containment Upon Arrival/Departure




2. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers




3. 149 Storytime: Filter Change



4. 149 Storytime: Temperature and Humidity






5. 201A Staff Only: Containment Upon Arrival/Departure



6. 201A Staff Only: Equipment

10 - Zip Post





7. 303 Storage: Containment Upon Arrival/Departure



8. 303 Storage: Equipment

2 - Zip Post



9. 305 Pioneer: Equipment

4 - Zip Post



10. 305 Pioneer: Containment Upon Arrival/Departure




11. 311 Local History: Containment Upon Arrival/Departure



12. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



13. Exterior: Temperature and Humidity



14. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord






15. Third Floor - Main Area: Filter Change




16. Third Floor - Main Area: Temperature and Humidity



17. 311 Local History: Filter Change





18. 311 Local History: Temperature and Humidity



19. Exterior: Equipment

2 - 20' Conex Boxes





20. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure





21. First Floor - Bay Windows (Children's Area): Equipment

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





22. First Floor - Bay Windows (Children's Area): Filter Change







23. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



24. Second Floor - Main Area: Filter Change



25. Second Floor - Main Area: Temperature and Humidity



26. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



27. First Floor - Bay Windows (Children's Area): Temperature and Humidity






28. First Floor - Main Area: Equipment

2 - Air Scrubbers



29. Second Floor - Southeast Corner: Equipment


- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord





30. Second Floor - Southeast Corner: Filter Change






31. Second Floor - Southeast Corner: Temperature and Humidity




32. Stairwell: Containment Upon Arrival/Departure



33. Stairwell: Equipment

- 2 - Air Scrubbers
- 1 - Zip Post
- 3 - 100' Extension Cords
- 2 - 50' Extension Cords



34. Stairwell: Filter Change





35. Stairwell: Temperature and Humidity



36. First Floor - Main Area: Filter Change



37. First Floor - Main Area: Temperature and Humidity



38. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



39. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers



40. First Floor - Southwest Vestibule: Filter Change






41. First Floor - Southwest Vestibule: Temperature and Humidity



42. Garage: Containment Upon Arrival/Departure




43. Main Entrance - Children's Area: Containment Upon Arrival/Departure





44. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers



45. Main Entrance - Children's Area: Filter Change





46. Main Entrance - Children's Area: Temperature and Humidity



47. SO 115: Containment Upon Arrival/Departure






48. SO 115: Equipment

- 6 - Air Scrubbers
- 4 - Zip Post



49. SO 115: Filter Change






50. SO 115: Temperature and Humidity






51. Garage: Equipment

- 4 - Air Scrubbers
- 1 - Fogger
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord





52. Garage: Filter Change



53. Garage: Temperature and Humidity



54. Overall: Equipment

- 72 - Zip Post
- 36 - Air Scrubbers
- 3 - Foggers
- 5 - 50' Extension Cords
- 2 - 100' Extension Cords
- 2 - 25' Extension Cords