

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sat 12/30/2023

Job #

## Weather

6:00 AM

30° 

Clear

Wind: 6 MPH | Precipitation: .0" | Humidity: 78%

12:00 PM

53° 

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 39%

4:00 PM

61° 

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 26%

## Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

## General Notes

### 1. Exterior: Equipment

2 - 20' Conex Boxes



### 2. Exterior: Temperature and Humidity



### 3. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



### 4. Third Floor - Main Area: Filter Change



### 5. Third Floor - Main Area: Temperature and Humidity



### 6. 303 Storage: Containment Upon Arrival/Departure





**7. 303 Storage: Equipment**

2 - Zip Post



**8. 305 Pioneer: Containment Upon Arrival/Departure**



**9. 305 Pioneer: Equipment**

4 - Zip Post



**10. 311 Local History: Containment Upon Arrival/Departure**







### 11. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



### 12. 311 Local History: Filter Change




### 13. 311 Local History: Temperature and Humidity





#### 14. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



#### 15. Second Floor - Main Area: Filter Change



#### 16. Second Floor - Main Area: Temperature and Humidity




#### 17. Second Floor - Southeast Corner: Containment Upon Arrival/Departure







**18. 201A Staff Only: Containment Upon Arrival/Departure**




**19. 201A Staff Only: Equipment**

**10 - Zip Post**








**20. Second Floor - Southeast Corner: Equipment**

- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord








21. Second Floor - Southeast Corner: Filter Change





**22. Second Floor - Southeast Corner: Temperature and Humidity**




**23. First Floor - Main Area: Equipment**

2 - Air Scrubbers





**24. First Floor - Main Area: Filter Change**



**25. First Floor - Main Area: Temperature and Humidity**




**26. 149 Storytime: Containment Upon Arrival/Departure**






**27. 149 Storytime: Equipment**



- 5 - Zip Post
- 2 - Air Scrubbers




**28. 149 Storytime: Filter Change**







**29. 149 Storytime: Temperature and Humidity**




**30. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure**



**31. First Floor - Bay Windows (Children's Area): Equipment**

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





32. First Floor - Bay Windows (Children's Area): Filter Change





**33. First Floor - Bay Windows (Children's Area): Temperature and Humidity**



**34. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**





**35. First Floor - Southwest Vestibule: Equipment**

- 2 - Zip Post
- 2 - Air Scrubbers



**36. First Floor - Southwest Vestibule: Filter Change**




**37. First Floor - Southwest Vestibule: Temperature and Humidity**






**38. Main Entrance - Children's Area: Containment Upon Arrival/Departure**





**39. Main Entrance - Children's Area: Equipment**



- 10 - Zip Post
- 3 - Air Scrubbers







40. Main Entrance - Children's Area: Filter Change





### 41. Main Entrance - Children's Area: Temperature and Humidity



### 42. Stairwell: Containment Upon Arrival/Departure



### 43. Stairwell: Equipment



- 5 - Air Scrubbers
- 1 - Zip Post
- 2 - 100' Extension Cords
- 1 - Fogger







**44. Stairwell: Filter Change**




**45. Stairwell: Temperature and Humidity**



**46. Garage: Containment Upon Arrival/Departure**





**47. Garage: Equipment**

- 4 - Air Scrubbers
- 1 - Fogger
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord



**48. SO 115: Containment Upon Arrival/Departure**





**49. SO 115: Equipment**

- 9 - Air Scrubbers
- 4 - Zip Post





50. Garage: Filter Change








**51. SO 115: Temperature and Humidity**



**52. SO 115: Filter Change**







53. Garage: Temperature and Humidity





**54. Overall: Equipment**

72 - Zip Post

42 - Air Scrubbers

3 - Foggers

5 - 50' Extension Cords

2 - 100' Extension Cords

2 - 25' Extension Cords