

Date Tue 12/19/2023

Job #

Weather

6:00 AM

33° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 56%

12:00 PM

50° 

Clear

Wind: 21 MPH | Precipitation: .0" | Humidity: 34%

4:00 PM

54° 

Clear

Wind: 18 MPH | Precipitation: .0" | Humidity: 36%


Work Logs

Name	Description
City of Norman Central Library - Mold	<p>Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technician began remediation in the stairwell, followed by an antimicrobial fogging of the area.</p> <p>Cavins technician finished setting up the cross - contamination barrier in SO 115. Upon completion of the cross - contamination barrier, Cavins technicians began remediation of the affected areas.</p>
Total	

General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Exterior: Temperature and Humidity



3. 305 Pioneer: Equipment

4 - Zip Post



4. 305 Pioneer: Containment Upon Arrival/Departure



5. 303 Storage: Containment Upon Arrival/Departure



6. 303 Storage: Equipment

2 - Zip Post



7. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



8. Third Floor - Main Area: Filter Change



9. Third Floor - Main Area: Temperature and Humidity




10. 311 Local History: Containment Upon Arrival/Departure






11. 311 Local History: Equipment


- 2 - Air Scrubbers
- 1 - Fogger



12. 311 Local History: Filter Change



13. 311 Local History: Temperature and Humidity








14. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



15. Second Floor - Main Area: Filter Change




16. Second Floor - Main Area: Temperature and Humidity



17. Overall: Equipment

- 72 - Zip Post
- 41 - Air Scrubbers
- 5 - Foggers
- 7 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 3 - HEPA Vacuums

18. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



19. Second Floor - Southeast Corner: Equipment


- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord





20. Second Floor - Southeast Corner: Filter Change






21. Second Floor - Southeast Corner: Temperature and Humidity






22. 201A Staff Only: Containment Upon Arrival/Departure




23. 201A Staff Only: Equipment

10 - Zip Post





24. Stairwell: Containment Upon Arrival/Departure









25. Stairwell: Equipment

- 5 - Air Scrubbers
- 3 - 100' Extension Cords
- 2 - 50' Extension Cords
- 1 - Zip Post
- 1 - Fogger
- 2 - Hepa Vacuums





26. Stairwell: Filter Change



27. Stairwell: Temperature and Humidity



28. 149 Storytime: Containment Upon Arrival/Departure



29. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



30. 149 Storytime: Filter Change



31. 149 Storytime: Temperature and Humidity




32. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




33. First Floor - Bay Windows (Children's Area): Equipment

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord



34. First Floor - Bay Windows (Children's Area): Filter Change



35. First Floor - Bay Windows (Children's Area): Temperature and Humidity






36. First Floor - Main Area: Equipment

2 - Air Scrubbers



37. First Floor - Main Area: Filter Change



38. First Floor - Main Area: Temperature and Humidity



39. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure





40. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers



41. First Floor - Southwest Vestibule: Filter Change






42. First Floor - Southwest Vestibule: Temperature and Humidity




43. SO 115: Containment Upon Arrival/Departure



44. SO 115: Equipment

- 4 - Zip Post
- 8 - Air Scrubbers
- 1 - HEPA Vacuum
- 1 - 50' Extension Cord
- 1 - Fogger





45. SO 115: Temperature and Humidity





46. Garage: Containment Upon Arrival/Departure



47. Garage: Equipment

- 4 - Air Scrubbers
- 2 - Foggers
- 1 - 50' Extension Cord
- 1 - 25' Extension Cord





48. Garage: Temperature and Humidity



49. Main Entrance - Children's Area: Containment Upon Arrival/Departure



50. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers





51. Main Entrance - Children's Area: Filter Change










52. Main Entrance - Children's Area: Temperature and Humidity




53. SO 115: Filter Change







54. Garage: Filter Change






55. Stairwell: Remediation





56. SO 115: Cross-Contamination Barrier Installation





57. Stairwell: Anti-Microbial Fog Treatment



58. SO 115: Mold Demo/Remediation

