

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 12/20/2023

Job #

Weather

6:00 AM

42° 

Clear

Wind: 14 MPH | Precipitation: .0" | Humidity: 80%

12:00 PM

52° 

Overcast

Wind: 17 MPH | Precipitation: .0" | Humidity: 86%

4:00 PM

56° 

Overcast

Wind: 17 MPH | Precipitation: .0" | Humidity: 76%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians continued to remediate the stairwell, upon remediation additional microbial growth was found at the landing between the roof access and the third floor. Cavins technician fogged the stairwell with an antimicrobial solution upon departure. Cavins technicians continued demo and remediation in SO 115.
Total	


General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Exterior: Temperature and Humidity



3. 303 Storage: Containment Upon Arrival/Departure



4. 303 Storage: Equipment

2 - Zip Post



5. 305 Pioneer: Containment Upon Arrival/Departure




6. 311 Local History: Containment Upon Arrival/Departure








7. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



8. 311 Local History: Filter Change



9. 311 Local History: Temperature and Humidity




10. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



11. Third Floor - Main Area: Filter Change



12. Third Floor - Main Area: Temperature and Humidity




13. 201A Staff Only: Containment Upon Arrival/Departure



14. 201A Staff Only: Equipment

10 - Zip Post






15. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




16. Second Floor - Southeast Corner: Equipment








- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord







17. Second Floor - Southeast Corner: Filter Change



18. Second Floor - Southeast Corner: Temperature and Humidity




19. Second Floor - Main Area: Equipment


- 2 - Air Scrubbers
- 1 - 25' Extension Cord



20. Second Floor - Main Area: Filter Change



21. Second Floor - Main Area: Temperature and Humidity



22. 149 Storytime: Containment Upon Arrival/Departure



23. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers




24. 149 Storytime: Filter Change



25. 149 Storytime: Temperature and Humidity




26. Stairwell: Containment Upon Arrival/Departure





27. Stairwell: Equipment

- 5 - Air Scrubbers
- 1 - Zip Post
- 3 - 100' Extension Cords
- 2 - 50' Extension Cords
- 2 - Hepa Vacuums
- 1 - Fogger



28. Stairwell: Filter Change





29. Stairwell: Temperature and Humidity




30. 305 Pioneer: Equipment



4 - Zip Post







31. Stairwell: Additional Microbial Growth





32. Stairwell: Remediation





33. So 115: Remediation






34. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure



35. First Floor - Bay Windows (Children's Area): Equipment


- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





36. First Floor - Bay Windows (Children's Area): Filter Change







37. First Floor - Bay Windows (Children's Area): Temperature and Humidity



38. First Floor - Main Area: Filter Change





39. First Floor - Main Area: Equipment

2 - Air Scrubbers



40. First Floor - Main Area: Temperature and Humidity



41. Main Entrance - Children's Area: Containment Upon Arrival/Departure




42. Main Entrance - Children's Area: Equipment

10 - Zip Post
3 - Air Scrubbers



43. Main Entrance - Children's Area: Filter Change





44. Main Entrance - Children's Area: Temperature and Humidity



45. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




46. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers




47. First Floor - Southwest Vestibule: Filter Change



48. First Floor - Southwest Vestibule: Temperature and Humidity



49. SO 115: Containment Upon Arrival/Departure













50. SO 115: Equipment


- 9 - Air scrubbers
- 4 - Zip Post
- 1 - Hepa Vac
- 1 - 50' Extension cord
- 1 - Fogger





51. SO 115: Filter Change





52. SO 115: Temperature and Humidity






53. Garage: Containment Upon Arrival/Departure




54. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers



55. Garage: Filter Change



56. Garage: Temperature and Humidity



57. Overall: Equipment

- 72 - Zip Post
- 42 - Air Scrubbers
- 8 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 5 - Foggers
- 3 - Hepa Vacuums

58. Stairwell: Anti Microbial Fog Treatment

