

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Thu 12/21/2023

Job #

Weather

6:00 AM

54°

Overcast

Wind: 13 MPH | Precipitation: .0" | Humidity: 77%

12:00 PM

59°

Overcast

Wind: 16 MPH | Precipitation: .0" | Humidity: 82%

4:00 PM

61°

Overcast

Wind: 11 MPH | Precipitation: .0" | Humidity: 83%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians continued remediation of SO 115.
Total	

General Notes

1. Exterior: Equipment


2 - 20' Conex Boxes



2. Exterior: Temperature and Humidity



3. 303 Storage: Containment Upon Arrival/Departure




4. 303 Storage: Equipment

2 - Zip Post



5. 305 Pioneer: Containment Upon Arrival/Departure




6. 305 Pioneer: Equipment

4 - Zip Post



7. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



8. Third Floor - Main Area: Filter Change



9. Third Floor - Main Area: Temperature and Humidity




10. 311 Local History: Containment Upon Arrival/Departure






11. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



12. 311 Local History: Filter Change



13. 311 Local History: Temperature and Humidity




14. 201A Staff Only: Containment Upon Arrival/Departure



15. 201A Staff Only: Equipment


10 - Zip Post







16. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



17. Second Floor - Main Area: Filter Change



18. Second Floor - Main Area: Temperature and Humidity



19. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



20. Second Floor - Southeast Corner: Equipment









- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord







21. Second Floor - Southeast Corner: Filter Change








22. Second Floor - Southeast Corner: Temperature and Humidity




23. Stairwell: Containment Upon Arrival/Departure







24. Stairwell: Equipment

- 5 - Air Scrubbers
- 3 - 100' Extension Cords
- 2 - 50' Extension Cords
- 2 - Hepa Vacuums
- 1 - Fogger
- 1 - Zip Post





25. Stairwell: Filter Change





26. Stairwell: Temperature and Humidity



27. 149 Storytime: Containment Upon Arrival/Departure




28. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



29. 149 Storytime: Filter Change




30. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure



31. First Floor - Bay Windows (Children's Area): Equipment



- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





32. First Floor - Bay Windows (Children's Area): Filter Change









33. First Floor - Bay Windows (Children's Area): Temperature and Humidity



34. First Floor - Main Area: Filter Change




35. First Floor - Main Area: Equipment

2 - Air Scrubbers



36. First Floor - Main Area: Temperature and Humidity




37. Main Entrance - Children's Area: Containment Upon Arrival/Departure




38. Main Entrance - Children's Area: Equipment


- 10 - Zip Post
- 3 - Air Scrubbers





39. Main Entrance - Children's Area: Filter Change





40. Main Entrance - Children's Area: Temperature and Humidity



41. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




42. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers






43. First Floor - Southwest Vestibule: Filter Change



44. First Floor - Southwest Vestibule: Temperature and Humidity





45. SO 115: Containment Upon Arrival/Departure













46. SO 115: Equipment


- 9 - Air Scrubbers
- 4 - Zip Post
- 1 - Fogger
- 1 - Hepa Vacuum
- 1 - 50' Extension Cord





47. SO 115: Filter Change





48. SO 115: Temperature and Humidity



49. Garage: Containment Upon Arrival/Departure




50. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers



51. Garage: Filter Change



52. Garage: Temperature and Humidity



53. Overall: Equipment

- 72 - Zip Post
- 42 - Air Scrubbers
- 8 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 5 - Foggers
- 3 - Hepa Vacuums

54. So 115: Remediation

