

Date Tue 12/26/2023

Job #

## Weather

6:00 AM

32° 

Overcast

Wind: 10 MPH | Precipitation: .0" | Humidity: 59%

12:00 PM

45° 

Clear

Wind: 14 MPH | Precipitation: .0" | Humidity: 33%

4:00 PM

47° 

Partially cloudy

Wind: 16 MPH | Precipitation: .0" | Humidity: 36%

## Work Logs

Name	Description
Cavins Environmental	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

## General Notes

### 1. Exterior: Equipment

2 - 20' Conex Boxes



### 2. Garage: Temperature and Humidity






### 3. Overall: Equipment

- 72 - Zip Post
- 42 - Air Scrubbers
- 5 - Foggers
- 3 - Hepa Vacuums
- 8 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords

### 4. Garage: Equipment

- 4 - Air Scrubbers
- 2 - Foggers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Hepa Vac





**5. Garage: Containment Upon Arrival/Departure**



**6. 149 Storytime: Containment Upon Arrival/Departure**



**7. 149 Storytime: Equipment**

- 5 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger





**8. 149 Storytime Temperature and Humidity**





**9. 149 Storytime: Filter Change**






**10. 201A Staff Only: Containment Upon Arrival/Departure**



**11. 201A Staff Only: Equipment**

**10 - Zip Post**





**12. 303 Storage: Containment Upon Arrival/Departure**



**13. 303 Storage: Equipment**

2 - Zip Post



**14. 305 Pioneer: Containment Upon Arrival/Departure**




**15. 305 Pioneer: Equipment**

4 - Zip Post



**16. 311 Local History: Containment Upon Arrival/Departure**





**17. 311 Local History: Equipment**

- 2 - Air Scrubbers
- 1 - Fogger



**18. 311 Local History: Filter Changes**






**19. 311 Local History: Temperature and Humidity**



**20. Exterior: Temperature and Humidity**



**21. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure**



**22. First Floor - Bay Windows (Children's Area): Equipment**

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension cord





23. First Floor - Bay Windows (Children's Area): Temperature and Humidity





**24. First Floor - Bay Windows (Children's Area): Filter Change**



**25. First Floor - Main Area: Temperature and Humidity**



**26. First Floor - Main Area: Filter Change**



**27. First Floor - Main Area: Equipment**

**2 - Air Scrubbers**



**28. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**





**29. First Floor - Southwest Vestibule: Equipment**

- 2 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger



**30. First Floor - Southwest Vestibule: Filter Change**








**31. First Floor - Southwest Vestibule: Temperature and Humidity**



**32. Garage: Filter Change**









**33. Main Entrance - Children's Area: Containment Upon Arrival/Departure**





**34. Main Entrance - Children's Area: Equipment**

- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - Fogger





35. Main Entrance - Children's Area: Filter Change



**36. Main Entrance - Children's Area: Temperature and Humidity**



**37. Second Floor - Main Area: Equipment**

- 2 - Air Scrubbers
- 1 - 25' Extension cord



**38. Second Floor - Main Area: Filter Change**




**39. Second Floor - Main Area: Temperature and Humidity**








#### 40. Second Floor - Southeast Corner: Containment Upon Arrival/Departure





#### 41. Second Floor - Southeast Corner: Equipment









- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger







42. Second Floor - Southeast Corner: Filter Change





**43. Second Floor - Southeast Corner: Temperature and Humidity**




**44. SO 115: Containment Upon Arrival/Departure**




**45. SO 115: Equipment**


- 4 - Zip Post
- 9 - Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension Cord
- 1 - Hepa Vac



46. SO 115: Filter Change







#### 47. SO 115: Temperature and Humidity



#### 48. Stairwell: Containment Upon Arrival/Departure





#### 49. Stairwell: Equipment

- 5 - Air Scrubber
- 1 - Fogger
- 3 - 100' Extension Cords
- 2 - 50' Extension Cords
- 3 - Hepa Vacuumms





50. Stairwell: Filter Change








**51. Stairwell: Temperature and Humidity**



**52. Third Floor -Main Area: Equipment**

- 1 - Air Scrubber
- 1 - 25' Extension Cord



**53. Third Floor - Main Area: Temperature and Humidity**



**54. Third Floor - Main Area: Filter Change**

