

Date Thu 01/04/2024

Job #

Weather

6:00 AM

27° 

Clear

Wind: 5 MPH | Precipitation: .0" | Humidity: 92%

12:00 PM

49° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 56%

4:00 PM

52° 

Partially cloudy

Wind: 11 MPH | Precipitation: .0" | Humidity: 49%

Work Logs

Name	Description
Cavins Enviromental	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

General Notes

1. 303 Storage: Containment Upon Arrival/Departure



2. 303 Storage: Equipment

2 - Zip Post



3. Exterior: Equipment

2 - 20' Conex Boxes



4. Exterior: Temperature and Humidity



5. 305 Pioneer: Containment Upon Arrival/Departure



6. 305 Pioneer: Equipment

4 - Zip Post




7. 311 Local History: Containment Upon Arrival/Departure




8. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



9. 311 Local History: Filter Change






10. 311 Local History: Temperature and Humidity



11. Third Floor - Main Area: Equipment


- 1 - Air Scrubber
- 1 - 50' Extension Cord



12. Third Floor - Main Area: Filter Change



13. Third Floor - Main Area: Temperature and Humidity



14. 201A Staff Only: Containment Upon Arrival/Departure



15. 201A Staff Only: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers







16. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



17. Second Floor - Main Area: Filter Change






18. Second Floor - Main Area: Temperature and Humidity





19. Second Floor - Southeast Corner: Containment Upon Arrival/Departure









20. Second Floor - Southeast Corner: Equipment


- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord





21. Second Floor - Southeast Corner: Filter Change





22. Second Floor - Southeast Corner: Temperature and Humidity






23. Stairwell: Containment Upon Arrival/Departure




24. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - Hepa Vacuum
- 1 - Fogger
- 1 - Zip Post



25. Stairwell: Filter Change



26. Stairwell: Temperature and Humidity



27. 149 Storytime: Containment Upon Arrival/Departure







28. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



29. 149 Storytime: Filter Change





30. 149 Storytime: Temperature and Humidity





31. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




32. First Floor - Bay Windows (Children's Area): Equipment


- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





33. First Floor - Bay Windows (Children's Area): Filter Change





34. First Floor - Bay Windows (Children's Area): Temperature and Humidity




35. First Floor - Main Area: Equipment

2 - Air Scrubbers



36. First Floor - Main Area: Filter Change



37. First Floor - Main Area: Temperature and Humidity




38. Main Entrance - Children's Area: Containment Upon Arrival/Departure



39. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers



40. Main Entrance - Children's Area: Filter Change





41. Main Entrance - Children's Area: Temperature and Humidity



42. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




43. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers




44. First Floor - Southwest Vestibule: Filter Change



45. First Floor - Southwest Vestibule: Temperature and Humidity






46. SO 115: Containment Upon Arrival/Departure











47. SO 115: Equipment

- 4 - Zip Post
- 7 - Air Scrubbers
- 1 - Fogger





48. SO 115: Filter Change





49. SO 115: Temperature and Humidity



50. Garage: Containment Upon Arrival/Departure








51. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Fogger



52. Garage: Filter Change



53. Garage: Temperature and Humidity



54. Overall: Equipment

- 72 - Zip Post
- 42 - Air Scrubbers
- 4 - Foggers
- 3 - 100' Extension Cords
- 5 - 50' Extension Cords
- 2 - 25' Extension Cords
- 1 - Hepa Vacuum

55. 201A Staff Only - Temperature and Humidity



56. SO 115: Contents Cleaning

Contents cleaning was performed in SO 115. 95% of the contents were documented and labelled

