

Date Fri 01/05/2024

Job #

Weather

6:00 AM

38° 

Overcast

Wind: 15 MPH | Precipitation: .0" | Humidity: 92%

12:00 PM

38° 

Overcast

Wind: 12 MPH | Precipitation: .0" | Humidity: 98%

4:00 PM

41° 

Overcast

Wind: 5 MPH | Precipitation: .0" | Humidity: 94%

Work Logs

Name	Description
City of Norman Central Library - Mold	<p>Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians removed the floor in SO 115 to see if mold was running all the way down, most of the sheetrock ends at the footing. All affected sheetrock was double bagged and disposed of. Cavins technicians cleaned 201A. All surfaces were HEPA vacuumed, wiped down with an antimicrobial solution, and fogged.</p>
Total	

General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Exterior: Temperature and Humidity



3. 303 Storage: Containment Upon Arrival/Departure




4. 303 Storage: Equipment

2 - Zip Post




5. 305 Pioneer: Containment Upon Arrival/Departure




6. 305 Pioneer: Equipment

4 - Zip Post




7. 311 Local History: Containment Upon Arrival/Departure





8. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



9. 311 Local History: Filter Change






10. 311 Local History: Temperature and Humidity




11. Third Floor - Main Area: Equipment

- 1 - Air Scrubbers
- 1 - 50' Extension Cord



12. Third Floor - Main Area: Filter Change



13. Third Floor - Main Area: Temperature and Humidity




14. 201A Staff Only: Containment Upon Arrival/Departure



15. 201A Staff Only: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - Hepa Vacuum
- 1 - Fogger (Removed from stairwell)
- 1 - 50' Extension Cord





16. 201A Staff Only: Temperature and Humidity





17. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



18. Second Floor - Southeast Corner: Equipment









- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord








19. Second Floor - Southeast Corner: Filter Change





20. Second Floor - Southeast Corner: Temperature and Humidity






21. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord




22. Second Floor - Main Area: Filter Change





23. Second Floor - Main Area: Temperature and Humidity





24. Stairwell: Containment Upon Arrival/Departure












25. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - Hepa Vacuum
- 1 - Fogger





26. Stairwell: Filter Change



27. Stairwell: Temperature and Humidity



28. 149 Storytime: Containment Upon Arrival/Departure




29. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



30. 149 Storytime: Filter Change



31. 149 Storytime: Temperature and Humidity




32. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




33. First Floor - Bay Windows (Children's Area): Equipment

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord



34. First Floor - Bay Windows (Children's Area): Filter Change



35. First Floor - Bay Windows (Children's Area): Temperature and Humidity








36. First Floor - Main Area: Equipment

2 - Air Scrubbers



37. First Floor - Main Area: Filter Change









38. First Floor - Main Area: Temperature and Humidity



39. Main Entrance - Children's Area: Containment Upon Arrival/Departure




40. Main Entrance - Children's Area: Filter Change



41. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers



42. Main Entrance - Children's Area: Temperature and Humidity



43. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



44. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Post




45. First Floor - Southwest Vestibule: Filter Change



46. First Floor - Southwest Vestibule: Temperature and Humidity



47. SO 115: Containment Upon Arrival/Departure











48. SO 115: Equipment


- 4 - Zip Post
- 9 - Air Scrubbers
- 1 - Fogger





49. SO 115: Filter Change





50. SO 115: Temperature and Humidity





51. Garage: Containment Upon Arrival/Departure




52. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Fogger



53. Garage: Filter Change




54. Garage: Temperature and Humidity



55. Overall: Equipment


- 72 - Zip Post
- 44 - Air Scrubbers
- 2 - Hepa Vacuums
- 6 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 4 - Foggers

56. 201A: Cleaning




57. 201A Staff Only: Filter Change







58. SO 115: Floor Removal




59. SO 115: Affected Sheetrock





60. 201A: Antimicrobial Fog Treatment



61. SO 115 Contents:

Contents cleaning was performed in SO 115. 100% of the contents were documented and labelled

