

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 01/03/2024

Job #

Weather

6:00 AM

31° 

Clear

Wind: 5 MPH | Precipitation: .0" | Humidity: 92%

12:00 PM

45° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 62%

4:00 PM

52° 

Clear



Wind: 7 MPH | Precipitation: .0" | Humidity: 44%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians continued Phase 1 cleaning in the stairwell.
Total	

General Notes

1. 303 Storage: Containment Upon Arrival/Departure



2. 303 Storage: Equipment

2 - Zip Post



3. Exterior: Equipment


2 - 20' Conex Boxes



4. Exterior: Temperature and Humidity



5. 305 Pioneer: Containment Upon Arrival/Departure



6. 305 Pioneer: Equipment

4 - Zip Post



7. 311 Local History: Containment Upon Arrival/Departure







8. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



9. 311 Local History: Filter Change





10. 311 Local History: Temperature and Humidity




11. Third Floor - Main Area: Equipment


- 1 - Air Scrubber
- 1 - 50' Extension Cord



12. Third Floor - Main Area: Filter Change



13. Third Floor - Main Area: Temperature and Humidity



14. 201A Staff Only: Containment Upon Arrival/Departure




15. 201A Staff Only: Equipment

10 - Zip Post






16. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




17. Second Floor - Southeast Corner: Equipment

- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50' Extension Cord





18. Second Floor - Southeast Corner: Filter Change





19. Second Floor - Southeast Corner: Temperature and Humidity




20. Stairwell: Containment Upon Arrival/Departure




21. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - 50' Extension Cord
- 2 - Hepa Vacuums
- 1 - Fogger



22. Stairwell: Filter Change



23. Stairwell: Temperature and Humidity





24. Second Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 25' Extension Cord



25. Second Floor - Main Area: Filter Change



26. Second Floor - Main Area: Temperature and Humidity



27. 149 Storytime: Containment Upon Arrival/Departure




28. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



29. 149 Storytime: Filter Change



30. 149 Storytime: Temperature and Humidity





31. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure




32. First Floor - Bay Windows (Children's Area): Equipment


- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





33. First Floor - Bay Windows (Children's Area): Filter Change





34. First Floor - Bay Windows (Children's Area): Temperature and Humidity






35. First Floor - Main Area: Equipment

2 - Air Scrubbers



36. First Floor - Main Area: Filter Change





37. First Floor - Main Area: Temperature and Humidity



38. Main Entrance - Children's Area: Containment Upon Arrival/Departure



39. Main Entrance - Children's Area: Equipment


- 10 - Zip Post
- 3 - Air Scrubbers





40. Main Entrance - Children's Area: Filter Change





41. Main Entrance - Children's Area: Temperature and Humidity




42. First Floor - Southwest Vestibule: Containment Upon Arrival/ Departure




43. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers



44. First Floor - Southwest Vestibule: Temperature and Humidity



45. First Floor - Southwest Vestibule: Filter Change




46. SO 115: Containment Upon Arrival/Departure






47. SO 115: Equipment

- 4 - Zip Post
- 7 - Air Scrubbers



48. SO 115: Filter Change






49. SO 115: Temperature and Humidity





50. Garage: Containment Upon Arrival/Departure









51. Garage: Equipment

- 4 - Air Scrubbers
- 1 - Fogger
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord





52. Garage: Filter Change




53. Garage: Temperature and Humidity



54. Overall: Equipment

- 72 - Zip Post
- 38 - Air Scrubbers
- 4 - Foggers
- 2 - Hepa Vacuums
- 6 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords

55. Stairwell: Phase 1 Cleaning



56. SO 115: Contents Cleaning

Contents cleaning was performed in SO 115. 85% of the contents were documented and labelled

