

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sun 01/07/2024

Job #

Weather

6:00 AM

27° 

Clear

Wind: 3 MPH | Precipitation: .0" | Humidity: 91%

12:00 PM

49° 

Clear

Wind: 18 MPH | Precipitation: .0" | Humidity: 45%

4:00 PM

54° 

Clear

Wind: 17 MPH | Precipitation: .0" | Humidity: 41%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

General Notes

1. 303 Storage: Containment Upon Arrival/Departure



2. 303 Storage: Equipment

2 - Zip Posts



3. 305 Pioneer: Containment Upon Arrival/Departure




4. 311 Local History: Containment Upon Arrival/Departure








5. 305 Pioneer: Equipment

4 - Zip Posts



6. 311 Local History: Filter Change



7. 311 Local History: Temperature and Humidity



8. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger




9. Exterior: Equipment

- 2 - 20' Conex Boxes



10. Third Floor - Main Area: Equipment
1 - Air Scrubber
1 - 50' Extension Cord





11. Third Floor - Main Area: Filter Change




12. Third Floor - Main Area: Temperature and Humidity



13. 201A Staff Only: Containment Upon Arrival/Departure






14. 201A Staff Only: Anti Microbial Fog Treatment



15. 201A Staff Only: Equipment

- 10 - Zip Posts
- 3 - Air Scrubbers
- 1 - Fogger





16. 201A Staff Only: Filter Change




17. 201A Staff Only: Temperature and Humidity



18. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord




19. Second Floor - Main Area: Filter Change



20. Second Floor - Main Area: Temperature and Humidity



21. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



22. Stairwell: Equipment



- 4 - Air Scrubbers
- 1 - Zip Post
- 3 - 100' Extension Cords
- 1 - 50' Extension Cord






23. Second Floor - Southeast Corner: Equipment

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger







24. Second Floor - Southeast Corner: Filter Change




25. Second Floor - Southeast Corner: Temperature and Humidity




26. Stairwell: Containment Upon Arrival/Departure



27. Stairwell: Filter Change





28. Stairwell: Temperature and Humidity




29. 149 Story Time: Containment Upon Arrival/Departure







30. 149 Story Time: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers






31. 149 Story Time: Filter Change



32. 149 Story Time: Temperature and Humidity









33. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure








34. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





35. First Floor - Bay Window's (Children's Area): Filter Change



36. First Floor - Bay Window's(Children's Area): Temperature and Humidity




37. First Floor - Main Area: Equipment

2 - Air Scrubbers



38. First Floor - Main Area: Filter Change



39. First Floor - Main Area: Temperature and Humidity



40. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



41. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Posts
- 2 - Air Scrubbers



42. First Floor - Southwest Vestibule: Temperature and Humidity






43. Main Entrance - Children's Area: Containment Upon Arrival/Departure







44. Main Entrance - Children's Area: Equipment

- 10 - Zip Posts
- 3 - Air Scrubbers





45. Main Entrance - Children's Area: Filter Change



46. Main Entrance - Children's Area: Temperature and Humidity




47. Garage: Containment Upon Arrival/Departure



48. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cord
- 1 - 25' Extension Cord
- 2 - Foggers





49. Garage: Temperature and Humidity



50. First Floor - Southwest Vestibule: Filter Change




51. Overall: Equipment

- 72 - Zip Posts
- 44 - Air Scrubbers
- 3 - 100' Extension Cords
- 5 - 50' Extension Cords
- 2 - 25' Extension Cords
- 4 - Foggers

52. Exterior: Temperature and Humidity






53. SO 115: Containment Upon Arrival/Departure




54. SO 115: Equipment

- 9 - Air Scrubbers
- 4 - Zip Posts





55. SO 115: Filter Change





56. SO 115: Temperature and Humidity



57. Garage: Filter Change

