

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Mon 01/08/2024

Job #

## Weather

6:00 AM

41°

Rain, Overcast

Wind: 18 MPH | Precipitation: .07" | Humidity: 84%

12:00 PM

44°

Overcast

Wind: 13 MPH | Precipitation: .0" | Humidity: 94%

4:00 PM

51°

Clear

Wind: 11 MPH | Precipitation: .0" | Humidity: 78%

## Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technicians worked on the cleaning phase in SO 115. All debris removed from the area was wiped down with an antimicrobial solution to avoid cross contamination before being disposed of. An antimicrobial fogging was performed in SO 115 upon leaving for the day.
Total	

## General Notes

### 1. 311 Local History: Set contents cleaning room




### 2. 149 Story Time: Containment Upon Arrival/Departure





### 3. 149 Story Time: Equipment

- 2 - Air Scrubbers
- 5 - Zip Posts
- 1 - Fogger



### 4. 149 Story Time: Filter Change:








**5. 149 Story Time: Temperature and Humidity**






**6. 201A Staff Only: Containment Upon Arrival/Departure**



**7. 201A Staff Only: Equipment**

- 3 - Air Scrubbers
- 10 - Zip Posts
- 1 - Fogger





**8. 201A Staff Only: Temperature and Humidity**



**9. 303 Storage: Containment Upon Arrival/Departure**



**10. 303 Storage: Equipment**

2 - Zip Posts



**11. 305 Pioneer: Containment Upon Arrival/Departure**



**12. 305 Pioneer: Equipment**

4 - Zip Posts





**13. 311 Local History: Containment Upon Arrival/Departure**







14. 311 Local History: Equipment

- 3 - Air Scrubbers
- 1 - Fogger



15. 311 Local History: Filter Change






**16. 311 Local History: Temperature and Humidity**



**17. Exterior: Equipment**


2 - 20' Conex Boxes



**18. Exterior: Temperature and Humidity**





**19. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure**




**20. First Floor - Bay Window's (Children's Area): Equipment**


- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger








21. First Floor - Bay Window's (Children's Area): Filter Change





**22. First Floor - Bay Window's(Children's Area): Temperature and Humidity**



**23. First Floor - Main Area: Equipment**

**2 - Air Scrubbers**






**24. First Floor - Main Area: Temperature and Humidity**



**25. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**




**26. First Floor - Main Area: Filter Change**





**27. First Floor - Southwest Vestibule: Equipment**

- 2 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger







**28. First Floor - Southwest Vestibule: Filter Change**



**29. First Floor - Southwest Vestibule: Temperature and Humidity**




**30. Garage: Containment Upon Arrival/Departure**








**31. Garage: Equipment**

- 4 - Air Scrubbers
- 2 - 50' Extension Cord
- 1 - 25' Extension Cord
- 2- Foggers





**32. Garage: Filter Change**



**33. Garage: Temperature and Humidity**









### 34. Main Entrance - Children's Area: Containment Upon Arrival/Departure







### 35. Main Entrance - Children's Area: Equipment

- 3 - Air Scrubbers
- 10 - Zip Posts
- 1 - Fogger (same one)





36. Main Entrance - Children's Area: Filter Change





**37. Main Entrance - Children's Area: Temperature and Humidity**





**38. Overall: Equipment**


- 45- Air Scrubbers (1 added to 311 local history for content cleaning room)
- 72 - Zip Posts
- 5 - HEPA vacs
- 4 - Foggers
- 6 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords
- 2 - conex boxes

**39. Second Floor - Main Area: Equipment**

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



**40. Second Floor - Main Area: Filter Change**





**41. Second Floor - Main Area: Temperature and Humidity**








**42. Second Floor - Southeast Corner: Containment Upon Arrival/Departure**






**43. Second Floor - Southeast Corner: Equipment**

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger





44. Second Floor - Southeast Corner: Filter Change





**45. Second Floor - Southeast Corner: Temperature and Humidity**





**46. SO 115: Containment Upon Arrival/Departure**









47. SO 115: Equipment

- 9 - Air Scrubbers
- 5 - Hepa Vacs
- 4 - Zip Post
- 1 - Fogger






48. SO 115: Filter Change







49. SO 115: Temperature and Humidity






### 50. SO 115: Phase 1 cleaning



### 51. Stairwell: Equipment


- 4 - Air Scrubbers
- 1 - Zip Post
- 1 - Hepa Vac
- 1 - Fogger
- 3 - 100'
- 1 - 50'



**52. Stairwell: Containment Upon Arrival/Departure**



**53. Stairwell: Filter Change**




**54. Stairwell: Temperature and Humidity**



**55. Third Floor - Main Area: Equipment**

- 1 - Air Scrubber
- 1 - 50' Extension Cord




**56. Third Floor - Main Area: Filter Change**



**57. Third Floor - Main Area: Temperature and Humidity**



**58. SO 115: Antimicrobial Fog Treatment**



59. SO 115: Antimicrobial Wipe Down

