

Date Sat 01/06/2024

Job #

Weather

6:00 AM

36° 

Overcast

Wind: 10 MPH | Precipitation: .0" | Humidity: 86%

12:00 PM

42° 

Overcast

Wind: 8 MPH | Precipitation: .0" | Humidity: 71%

4:00 PM

46° 

Partially cloudy

Wind: 12 MPH | Precipitation: .0" | Humidity: 61%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	

General Notes

1. 303 Storage: Equipment


2 - Zip Posts



2. 303 Storage: Containment Upon Arrival/Departure



3. 305 Pioneer: Containment Upon Arrival/Departure




4. 305 Pioneer: Equipment

4 - Zip Posts



5. 311 Local History: Filter Change





6. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



7. 311 Local History: Containment Upon Arrival/Departure




8. 311 Local History: Temperature and Humidity



9. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord




10. Third Floor - Main Area: Filter Change



11. Third Floor - Main Area: Temperature and Humidity




12. 201A Staff Only: Containment Upon Arrival/Departure




13. 201A Staff Only: Equipment

- 10 - Zip Posts
- 3 - Air Scrubbers



14. 201A Staff Only: Filter Change





15. 201A Staff Only: Temperature and Humidity



16. Stairwell: Containment Upon Arrival/Departure








17. Stairwell: Equipment

- 4 - Air Scrubbers
- 4 - 100' Extension Cords
- 1 - 50' Extension Cord



18. Stairwell: Filter Change





19. Stairwell: Temperature and Humidity




20. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




21. Second Floor - Southeast Corner: Equipment



- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger








22. Second Floor - Southeast Corner: Filter Change





23. Second Floor - Southeast Corner: Temperature and Humidity



24. Second Floor - Main Area: Filter Change





25. Second Floor - Main Area: Equipment



- 2 - Air Scrubbers
- 1 - 25' Extension Cord



26. Second Floor - Main Area: Temperature and Humidity



27. 201A Staff Only: Anti Microbial Fog Treatment





28. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure



29. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Post
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





30. First Floor - Bay Window's (Children's Area): Filter Change



31. First Floor - Bay Window's(Children's Area): Temperature and Humidity



32. 149 Story Time: Containment Upon Arrival/Departure




33. 149 Story Time: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers




34. 149 Story Time: Filter Change



35. 149 Story Time: Temperature and Humidity




36. Main Entrance - Children's Area: Containment Upon Arrival/Departure






37. Main Entrance - Children's Area: Equipment

- 10 - Zip Posts
- 3 - Air Scrubbers



38. Main Entrance - Children's Area: Filter Change





39. Main Entrance - Children's Area: Temperature and Humidity



40. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Posts
- 2 - Air Scrubbers






41. First Floor - Southwest Vestibule: Filter Change



42. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




43. First Floor - Southwest Vestibule: Temperature and Humidity



44. SO 115: Equipment

- 9 - Air Scrubbers
- 4 - Zip Posts













45. SO 115: Containment Upon Arrival/Departure



46. SO 115: Filter Change







47. SO 115: Temperature and Humidity



48. Garage: Equipment





- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers



49. Garage: Containment Upon Arrival/Departure



50. Garage: Filter Change



51. Garage: Temperature and Humidity



52. First Floor - Main Area: Equipment




2 - Air Scrubbers



53. First Floor - Main Area: Temperature and Humidity



54. First Floor - Main Area: Filter Change





55. Exterior: Temperature and Humidity



56. Overall: Equipment

- 72 - Zip Posts
- 44 - Air Scrubbers
- 3 - 100' Extension Cords
- 5 - 50' Extension Cords
- 2 - 25' Extension Cords
- 4 - Fogger