

Date Tue 01/09/2024

Job #

Weather

6:00 AM

27° 

Overcast

Wind: 27 MPH | Precipitation: .0" | Humidity: 77%

12:00 PM

34° 

Overcast

Wind: 24 MPH | Precipitation: .0" | Humidity: 69%

4:00 PM

39° 

Clear

Wind: 17 MPH | Precipitation: .0" | Humidity: 52%

Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Cavins technician continued to inventory, clean/decontaminate, and store items from 311 Local History. Cavins technician worked on the cleaning phase in SO 115. A fogging with an antimicrobial solution was performed in SO 115 as well.
Total	

General Notes

1. Exterior: Temperature and Humidity



2. Exterior: Equipment

2 - 20' Conex Boxes



3. 303 Storage: Containment Upon Arrival/Departure



4. 305 Pioneer: Containment Upon Arrival/Departure




5. 305 Pioneer: Equipment

4 - Zip Post



6. 303 Storage: Equipment

2 - Zip Post



7. 311 Local History: Containment Upon Arrival/Departure




8. 311 Local History: Equipment

- 3 - Air Scrubbers
- 1 - Fogger
- 1 - Hepa Vac



9. 311 Local History: Filter Change



10. 311 Local History: Temperature and Humidity




11. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



12. Third Floor - Main Area: Filter Change



13. Third Floor - Main Area: Temperature and Humidity




14. 201A Staff Only: Containment Upon Arrival/Departure



15. 201A Staff Only: Equipment


- 10 - Zip Posts
- 3 - Air Scrubbers



16. 201A Staff Only: Temperature and Humidity




17. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



18. Second Floor - Southeast Corner: Equipment









- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord








19. Second Floor - Southeast Corner: Filter Change






20. Second Floor - Southeast Corner: Temperature and Humidity



21. Stairwell: Containment Upon Arrival/Departure



22. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - Zip Post




23. Stairwell: Temperature and Humidity





24. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord




25. Second Floor - Main Area: Filter Change




26. Second Floor - Main Area: Temperature and Humidity







27. SO 115: Containment Upon Arrival/Departure




28. SO 115: Antimicrobial fog treatment





29. SO 115: Cleaning Phase





**30. 201A: Post Remediation Verification Testing
Air Quality Testing/Temperature and Humidity**



31. Exterior: Air Quality Testing/Temperature and Humidity



32. 149 Storytime: Containment Upon Arrival/Departure




33. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers



34. 149 Storytime: Filter Change



35. 149 Storytime: Temperature and Humidity





36. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure



37. First Floor - Bay Windows (Children's Area): Equipment


- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cord





38. First Floor - Bay Windows (Children's Area): Filter Change





39. First Floor - Bay Windows (Children's Area): Temperature and Humidity



40. First Floor - Main Area: Equipment

2 - Air Scrubbers



41. First Floor - Main Area: Filter Change



42. First Floor - Main Area: Temperature and Humidity




43. Main Entrance - Children's Area: Containment Upon Arrival/Departure



44. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers



45. Main Entrance - Children's Area: Filter Change





46. Main Entrance - Children's Area: Temperature and Humidity



47. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



48. First Floor - Southwest Vestibule: Equipment

- 2 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger



49. First Floor - Southwest Vestibule: Filter Change








50. First Floor - Southwest Vestibule: Temperature and Humidity







51. SO 115: Equipment


- 9 - Air Scrubbers
- 5 - Hepa Vacuums
- 8 - 50' Extension Cords
- 1 - Fogger





52. SO 115: Filter Change





53. SO 115: Temperature and Humidity



54. Garage: Containment Upon Arrival/Departure










55. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers





56. Garage: Filter Change



57. Garage: Temperature and Humidity





58. Overall: Equipment

- 68 - Zip Post
- 45 - Air Scrubbers
- 6 - Hepa Vacuums
- 4 - Foggers
- 13 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords

59. 311 Local History: Cleaning/Decontamination







60. 311 Local History: Stored Items



61. Stairwell: Filter Change

