

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 01/10/2024

Job #

Weather

6:00 AM

30° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 65%

12:00 PM

47° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 39%

4:00 PM

57° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 32%


Work Logs

Name	Description
City of Norman Central Library - Mold	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading. Room 311 was prepped for demo. Floor protection was put down, furniture was moved away from the demo area, cleaned, and covered.
Total	

General Notes

1. Exterior: Equipment

2 - 20' Conex Boxes



2. Exterior: Temperature And Humidity



3. 303 Storage: Containment Upon Arrival/Departure



4. 303 Storage: Equipment

2 - Zip Posts



5. 305 Pioneer: Containment Upon Arrival/Departure



6. 305 Pioneer: Equipment

4 - Zip Posts



7. 311 Local History: Containment Upon Arrival/Departure




8. 311 Local History: Equipment

3 - Air Scrubbers



9. 311 Local History: Filter Change






10. 311 Local History: Temperature And Humidity



11. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord




12. Third Floor - Main Area: Filter Change




13. Third Floor - Main Area: Temperature And Humidity



14. 201A Staff Only: Containment Upon Arrival/Departure



15. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



16. Second Floor - Southeast Corner: Equipment







- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord








17. Second Floor - Southeast Corner: Filter Change





18. Second Floor - Southeast Corner: Temperature And Humidity



19. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



20. Second Floor - Main Area: Filter Change



21. Second Floor - Main Area: Temperature And Humidity




22. Stairwell: Containment Upon Arrival/Departure




23. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cords
- 1 - Zip Post
- 1 - Fogger






24. Stairwell: Filter Change



25. Stairwell: Temperature And Humidity





26. 149 Storytime: Containment Upon Arrival/Departure




27. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers



28. 149 Storytime: Filter Change



29. 149 Storytime: Temperature And Humidity



30. First Floor Main Area: Filter Change



31. First Floor Main Area: Equipment


2 - Air Scrubbers




32. First Floor Main Area: Temperature and Humidity



33. Main Entrance - Children’s Area: Containment Upon Arrival/Departure



34. First Floor - Bay Windows (Children’s Area): Containment Upon Arrival/Departure



35. First Floor Southwest Vestibule: Filter Change



36. First Floor Southwest Vestibule: Temperature and Humidity



37. First Floor Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Posts



38. First Floor Southwest Vestibule: Containment Upon Arrival/Departure



39. 201A Staff Only: Temperature and Humidity



40. 305 Pioneer: Temperature and Humidity




41. SO 115: Containment Upon Arrival/Departure



42. First Floor - Bay Windows (Children's Area): Temperature and Humidity




43. First Floor - Bay Windows (Children's Area): Filter Change



44. First Floor - Bay Windows (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cord







45. Main Entrance - Children's Area: Equipment

- 10 - Zip Post
- 3 - Air Scrubbers



46. Main Entrance - Children's Area: Filter Change
















47. Main Entrance - Children's Area: Temperature and Humidity



48. SO 115: Equipment


- 9 - Air Scrubbers
- 5 - Hepa Vacuums
- 8 - 50' Extension
- 1 - Fogger





49. SO 115: Filter Change





50. SO 115: Temperature and Humidity




51. Garage: Containment Upon Arrival/Departure






52. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 2 - Foggers





53. Garage: Filter Change



54. Garage: Temperature and Humidity



55. Overall: Equipment

- 68 - Zip Posts
- 42- Air Scrubbers
- 5 - Hepa Vacuums
- 4 - Foggers
- 13 - 50' Extension Cords
- 3 - 100' Extension Cords
- 2 - 25' Extension Cords

56. 311 Local History: Prepare For Demo

Installed floor protection where the previous furniture was stationed, moved desk away from demo wall and cleaned and recovered with protective plastic.



57. SO 115: Antimicrobial fog treatment



58. SO 115: Phase 1 cleaning
Hepa vac ceiling, walls and floor.

