

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sat 01/13/2024

Job #

Weather

6:00 AM

18° 

Clear

Wind: 7 MPH | Precipitation: .0" | Humidity: 78%

12:00 PM

16° 

Partially cloudy

Wind: 22 MPH | Precipitation: .0" | Humidity: 62%

4:00 PM

20° 

Clear

Wind: 23 MPH | Precipitation: .0" | Humidity: 52%

Work Logs

Name	Description
Cavins Environmental	Cavins Group arrived on site and suited up in proper PPE. Upon suiting up, Cavins technicians checked all containments and equipment for defects. All air scrubber filters were changed, temperature and humidity readings were taken in all containments, all three floors in the main area, and one exterior reading.
Total	




General Notes

1. 149 Storytime: Containment Upon Arrival/Departure





2. 149 Storytime: Equipment

- 2 - Air Scrubbers
- 5 - Zip Posts



3. 149 Storytime: Filter Change



4. 149 Storytime: Temperature and Humidity





5. 201A Staff Only: Containment Upon Arrival/Departure



6. 201A Staff Only: Equipment

10 - Zip Posts





7. 303 Storage: Containment Upon Arrival/Departure



8. 303 Storage: Equipment

2 - Zip Posts




9. 305 Pioneer: Containment Upon Arrival/Departure



10. 305 Pioneer: Equipment

4 - Zip Posts



11. 311 Local History: Containment Upon Arrival/Departure



12. 311 Local History: Equipment

- 2 - Air Scrubbers
- 1 - Fogger



13. 311 Local History: Filter Change






14. 311 Local History: Temperature and Humidity





15. Children's Area - Main Entrance: Containment Upon Arrival/Departure



16. Children's Area - Main Entrance: Equipment

- 3 - Air Scrubbers
- 10 - Zip Posts
- 1 - Fogger(same)





17. Children's Area - Main Entrance: Filter Change





18. Children's Area - Main Entrance: Temperature and Humidity



19. Exterior: Equipment

2 - 20' Conex Boxes



20. Third Floor - Main Area: Temperature and Humidity



21. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



22. Third Floor - Main Area: Filter Change



23. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25 Ft Extension Cord



24. Second Floor - Main Area: Filter Change





25. Second Floor - Southeast Corner: Equipment

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - Fogger
- 1 - 50 Ft Extension Cord








26. First Floor - Main Area: Equipment

2 - Air Scrubbers



27. Second Floor - Southeast Corner: Filter Change





28. First Floor - Main Area: Filter Change



29. First Floor - Main Area: Temperature and Humidity



30. Second Floor - Southeast Corner: Temperature and Humidity





31. Stairwell: Containment Upon Arrival/Departure





32. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cord
- 6 - 50' Extension Cord
- 4 - Hepa Vac
- 1 - Fogger
- 1 - Zip Post





33. Stairwell: Filter Change






34. Stairwell: Temperature and Humidity




35. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



36. Second Floor - Main Area: Temperature and Humidity



37. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



38. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Posts
- 1 - Fogger(same)



39. First Floor - Southwest Vestibule: Filter Change



40. First Floor - Southwest Vestibule: Temperature and Humidity




41. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure








42. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50 Ft Extension Cord
- 1 -Fogger





43. First Floor - Bay Window's (Children's Area): Filter Change



44. First Floor - Bay Window's (Children's Area): Temperature and Humidity





45. SO 115: Containment Upon Arrival/Departure








46. SO 115: Equipment

- 9 - Air Scrubbers
- 1 - Zip Post
- 1 - Fogger(same)





47. SO 115: Filter Change






48. SO 115: Temperature and Humidity



49. SO 115: Anti Microbial Fog Treatment




50. Garage: Containment Upon Arrival/Departure







51. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Fogger



52. Garage: Filter Change



53. Garage: Temperature and Humidity



54. Exterior: Temperature and Humidity



55. Overall: Equipment Count

- 41 - Air Scrubbers
- 69- Zip Posts
- 5 - Foggers
- 4 - Hepa Vac (Demo Hepa vac not included, not in use)
- 2 - 25 Ft Extension Cords
- 11- 50 Ft Extension Cords (added 2 50' extension cords to Stairwell 1/12)
- 3 - 100 Ft Extension Cords