

Date Sun 01/14/2024

Job #

Weather

6:00 AM

2° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 48%

12:00 PM

5° 

Overcast

Wind: 10 MPH | Precipitation: .12" | Humidity: 59%

4:00 PM

8° 

Partially cloudy

Wind: 14 MPH | Precipitation: .0" | Humidity: 62%

Work Logs


Name	Description
Cavins Environmental	Cavins environment inspected all containment, changed air scrubber filters, checked the temperature and humidity in common and containment areas, and fogged room SO 115.
Total	

General Notes

1. Third Floor - Main Area: Temperature and Humidity




2. Third Floor - Main Area: Filter Change




3. Third Floor - Main Area: Equipment





- 1 - Air Scrubber
- 1 - 50' Extension Cord




4. Stairwell: Temperature and Humidity



5. Stairwell: Filter Change







6. Stairwell: Equipment

- 4 - Air Scrubbers
- 3 - 100' Extension Cord
- 6- 50' Extension Cord
- 4 - Hepa Vac
- 1 - Fogger
- 1 - Zip Posts














7. Stairwell: Containment Upon Arrival/Departure




8. SO 115: Temperature and Humidity





9. SO 115: Filter Change






10. SO 115: Equipment

- 9 - Air Scrubbers
- 1 - Zip Post







11. SO 115: Containment Upon Arrival/Departure




12. SO 115: Antimicrobial Fog Treatment





13. Second Floor - Southeast Corner: Temperature and Humidity




14. Second Floor - Southeast Corner: Filter Change






15. Second Floor - Southeast Corner: Equipment

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - Fogger
- 1 - 50' Extension Cord






16. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



17. Second Floor - Main Area: Temperature and Humidity



18. Second Floor - Main Area: Filter Change



19. Second Floor - Main Area: Equipment

- 2- Air Scrubbers
- 1 - 25' Extension Cord







20. Overall: Equipment Count

- 41 - Air Scrubbers
- 69- Zip Posts
- 5 - Foggers
- 4 - Hepa Vac (Demo Hepa vac not included, not in use)
- 2 - 25 Ft Extension Cords
- 11- 50 Ft Extension Cords (added 2 50' extension cords to Stairwell 1/12)
- 3 - 100 Ft Extension Cords

21. Garage: Temperature and Humidity






22. Garage: Filter Change





23. Garage: Equipment

- 4 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - 25' Extension Cord
- 1 - Fogger





24. Garage: Containment Upon Arrival/Departure



25. First Floor - Southwest Vestibule: Temperature and Humidity



26. First Floor - Southwest Vestibule: Filter Change



27. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Posts




28. 303 Storage: Equipment

2 - Zip Posts



29. 303 Storage: Containment Upon Arrival/Departure



30. 305 Pioneer: Containment Upon Arrival/Departure



31. 305 Pioneer: Equipment

4 - Zip Posts



32. 311 Local History: Containment Upon Arrival/Departure



33. 311 Local History: Equipment


2 - Air Scrubber
1 - Fogger



34. 311 Local History: Temperature and Humidity



35. 311 Local History: Filter Change




36. 201A Staff Only: Equipment

10 - Zip Posts





37. 201A Staff Only: Containment Upon Arrival/Departure






38. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



39. First Floor - Main Area: Temperature and Humidity



40. First Floor - Main Area: Filter Change



41. First Floor - Main Area: Equipment


2 - Air Scrubbers



42. First Floor - Bay Window's (Children's Area): Temperature and Humidity




43. First Floor - Bay Window's (Children's Area): Filter Change




44. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 -Fogger



45. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure



46. Exterior: Temperature and Humidity




**47. Exterior: Equipment
2 - 20' Conex Boxes**



48. Children's Area - Main Entrance: Temperature and Humidity




49. Children's Area - Main Entrance: Filter Change



50. Children's Area - Main Entrance: Equipment

- 3 - Air Scrubbers
- 10 - Zip Posts





51. Children's Area - Main Entrance: Containment Upon Arrival/Departure



52. 149 Storytime: Containment Upon Arrival/Departure






53. 149 Storytime: Equipment

- 2 - Air Scrubbers
- 5 - Zip Posts



54. 149 Storytime: Filter Change





55. 149 Storytime: Temperature and Humidity

