

Date Tue 01/23/2024

Job #

Weather

6:00 AM

33° 

Overcast

Wind: 0 MPH | Precipitation: .0" | Humidity: 98%

12:00 PM

39° 

Overcast

Wind: 2 MPH | Precipitation: .0" | Humidity: 96%

4:00 PM

41° 

Rain, Overcast

Wind: 9 MPH | Precipitation: .0" | Humidity: 100%

Work Logs

Name	Description
Cavins Environmental	Cavins Group took temperature and humidity readings and Cavins Technician suited up in proper PPE, changed pre filters in air scrubbers, and continued remediation on Second Floor - Southeast Corner in study room and on top off over hang. The cleaning process continued in office 311. Demo continued in the children's bay window area. Removal of equipment and containment began in areas that passed post remediation verification testing.
Total	


General Notes

1. 311 Local History: Containment Upon Arrival/Departure







2. 311 Local History: Equipment


- 2 - Air Scrubbers
- 2 - Hepa Vac
- 1 - 50 Ft Extension Cord
- 1 - Fogger



3. 311 Local History: Filter Change



4. 311 Local History: Temperature And Humidity




5. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




6. Second Floor - Southeast Corner: Equipment







- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50 Ft Extension Cord







7. Second Floor - Southeast Corner: Filter Change





8. Second Floor - Southeast Corner: Temperature And Humidity




9. Stairwell: Containment Upon Arrival/Departure



10. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50 Ft Extension Cord



11. Third Floor - Main Area: Filter Change





12. Third Floor - Main Area: Temperature And Humidity




13. Second Floor - Main Area: Equipment
2 - Air Scrubbers
1 - 25 Ft Extension Cord



14. Second Floor - Main Area: Filter Change





15. Second Floor - Main Area: Temperature And Humidity




16. 311 Local History: Debris Hepa Vacuuming:



17. 311 Local History: Phase One Hepa Vacuuming and Cleaning







18. Second Floor - Southeast Corner: Study Room Remediation
 Microbial growth was found on back side of ceiling drywall



19. First Floor - Main Area: Equipment



20. First Floor - Main Area: Filter Change








21. First Floor - Main Area: Temperature And Humidity



22. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure





23. First Floor - Bay Window's (Children's Area):Equipment
 4 Air scrubbers
 12 Zip Posts
 1 50' Extension Cord





24. First Floor - Bay Window's (Children's Area): Filter Change









25. First Floor - Bay Window's (Children's Area): Temperature And Humidity


26. 149 Storytime: Equipment

- 5 - Zip Post
- 2 - Air Scrubbers
- 1 - Fogger



27. 149 Storytime: Filter Change





28. 149 Storytime: Containment Upon Arrival/Departure



29. 149 Storytime: Temperature And Humidity






30. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



31. First Floor - Southwest Vestibule: Equipment
2 - Zip Post
2 - Air Scrubbers



32. First Floor - Southwest Vestibule: Filter Change



33. First Floor - Southwest Vestibule: Temperature And Humidity



34. Main entrance - Children's Area: Containment Upon Arrival/Departure








35. Main entrance - Children's Area: Equipment
 10 - Zip Post
 3 - Air Scrubbers






36. Main entrance - Children's Area: Filter Change



37. Main entrance - Children's Area: Temperature And Humidity



38. First Floor - Bay Windows (Children's Area): Selective Demo





- 39. Overall: Equipment**
 51 - Zip Post
 24 - Air Scrubbers
 2 - Foggers
 2 - Hepa Vac
 1 - 25 Ft Extension Cord
 4 - 50 Ft Extension Cord
 2 - 20 Ft Conex



40. Exterior: Equipment



41. Exterior: Temperature And Humidity



42. 311 Local History: Anti microbial Fog Treatment



43. First Floor - Bay Window's (Children's Area): Water Trails

