

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Thu 01/25/2024

Job #

Weather

6:00 AM

40°

Overcast

Wind: 8 MPH | Precipitation: .0" | Humidity: 98%

12:00 PM

43°

Overcast

Wind: 6 MPH | Precipitation: .0" | Humidity: 99%

4:00 PM

45°

Overcast


Wind: 8 MPH | Precipitation: .0" | Humidity: 92%

Work Logs


Name	Description
Cavins Environmental	Cavins Group took temperature and humidity readings. suited up in proper PPE, and changed pre filters in air scrubbers. The cleaning process continued on the First Floor Bay Window area followed with antimicrobial fog treatment. Antimicrobial fog treatment was done in 311 Local History. The cleaning process continued on Second Floor Southeast Corner.
Total	

General Notes

- 1. Third Floor - Main Area: Equipment
 - 1 - Air Scrubber
 - 1 - 50 Ft Extension Cord



- 2. Third Floor - Main Area: Filter Change



3. Third Floor - Main Area: Temperature And Humidity



4. 311 Local History: Containment Upon Arrival/Departure



5. 311 Local History: Equipment 2 - Air Scrubbers 1 - Fogger



6. 311 Local History: Filter Change




7. 311 Local History: Temperature And Humidity




8. Second Floor - Southeast Corner: Continue phase 1 cleaning, hepa vac all surfaces, wipe down with anti microbial solution.





9. Second Floor - Southeast Corner: Temperature and Humidity



10. Second Floor - Southeast Corner: Equipment


22 - Zip Post




6 - Air Scrubbers

3 - 100 Ft Extension Cords

4 - 50 Ft Extension Cords

4 - Hepa Vac









11. 311 Local History: Antimicrobial Fog Treatment




12. Second Floor - Main Area: Equipment
2 - Air Scrubbers
1 - 25 Ft Extension Cord



13. Second Floor - Main Area: Filter Change








14. Second Floor - Main Area: Temperature And Humidity




15. Second Floor - Southeast Corner: Filter Change





16. First Floor - Bay Windows (Children's Area): Phase Two Hepa Vacuuming And Cleaning









17. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



18. First Floor - Main Area: Filter Change





19. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25 Ft Extension Cords



20. First Floor - Main Area: Temperature And Humidity




21. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure




22. First Floor - Bay Window's (Children's Area): Equipment
12 - Zip Posts
4 - Air Scrubbers
1 - Hepa Vacuum
1 - Fogger

2 - 50' Extension Cords



23. First Floor - Bay Window's (Children's Area): Filter Change





24. First Floor - Bay Window's (Children's Area): Temperature And Humidity




25. 149 Storytime: Containment Upon Arrival/Departure




26. 149 Storytime: Equipment
2 - Air Scrubbers
5 - Zip Post



27. 149 Storytime: Filter Change






28. 149 Storytime: Temperature And Humidity




29. Main Entrance - Children's Area: Containment Upon Arrival/Departure




30. Main Entrance - Children's Area: Equipment


- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - Fogger
- 1 - Debris Vacuum
- 1 - Hepa Vacuum
- 1 - 50' Extension Cord





31. Main Entrance - Children's Area: Filter Change





32. Main Entrance - Children's Area: Temperature And Humidity






33. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



34. First Floor - Southwest Vestibule: Equipment
 2 - Zip Post
 2 - Air Scrubbers




35. First Floor - Southwest Vestibule: Filter Change



36. First Floor - Southwest Vestibule: Temperature And Humidity



37. First Floor - Bay Windows (Children's Area): Anti Microbial Fog Treatment



38. Overall: Equipment


- 25 - Air Scrubbers
- 51 - Zip Post
- 5 - Hepa Vac
- 3 - Foggers
- 3 - 100 Ft Extension Cords
- 8 - 50 Ft Extension Cords
- 2 - 25 Ft Extension Cords
- 2 - 20 Ft Conex

39. Exterior: Equipment

- 2 - 20 Ft Conex



40. Exterior: Temperature And Humidity



41. Main Entrance - Children's Area: Phase One Hepa Vacuuming

