

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sun 01/28/2024

Job #

Weather

6:00 AM

30° 

Clear

Wind: 1 MPH | Precipitation: .0" | Humidity: 94%

12:00 PM

52° 

Clear

Wind: 0 MPH | Precipitation: .0" | Humidity: 58%

4:00 PM

61° 

Clear

Wind: 5 MPH | Precipitation: .0" | Humidity: 36%

Work Logs

Name	Description
Cavins Environmental	Cavins Group Arrived on site, took Temperature and Humidity readings of affected and main areas and one exterior. Cavins Technician suited up in proper PPE and changed all pre filters in air scrubbers within containments and main areas. Anti-microbial fog treatment was performed in 311 Local History, First Floor - Southwest Vestibule and Children's Area - Main Entrance.
Total	

General Notes

1. 149 Storytime: Containment Upon Arrival/Departure






2. 149 Storytime: Equipment

- 2 - Air Scrubbers
- 5 - Zip Post



3. 149 Storytime: Filter Change



4. 149 Storytime: Temperature And Humidity



5. 311 Local History: Antimicrobial Fog Treatment




6. 311 Local History: Containment Upon Arrival/Departure



7. 311 Local History: Equipment 2 - Air Scrubbers 1 - Fogger




8. 311 Local History: Filter Change




9. 311 Local History: Temperature And Humidity



**10. Exterior: Equipment
2 - 20 Ft Conex**





11. Exterior: Temperature And Humidity



12. First Floor - Bay Windows (Children's Area): Anti Microbial Fog Treatment




13. First Floor - Bay Window's (Children's Area): Containment Upon Arrival/Departure



14. First Floor - Bay Window's (Children's Area): Equipment

- 12 - Zip Posts
- 4 - Air Scrubbers
- 1 - 50' Extension Cords





15. First Floor - Bay Window's (Children's Area): Filter Change






16. First Floor - Bay Window's (Children's Area): Temperature And Humidity



17. First Floor - Main Area: Equipment
 3 - Air Scrubbers
 1 - 25 Ft Extension Cords



18. First Floor - Main Area: Temperature And Humidity



19. First Floor - Main Area: Filter Change



20. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




21. First Floor - Southwest Vestibule: Equipment
 2 - Zip Post
 2 - Air Scrubbers
 1 - Fogger



22. First Floor - Southwest Vestibule: Filter Change





23. First Floor - Southwest Vestibule: Temperature And Humidity



24. Main Entrance - Children's Area: Containment Upon Arrival/Departure





25. Main Entrance - Children's Area: Equipment


- 10 - Zip Post
- 3 - Air Scrubbers
- 1 - Fogger





26. Main Entrance - Children's Area: Filter Change







27. Main Entrance - Children's Area: Temperature And Humidity



28. Second Floor - Main Area: Filter Change





29. Second Floor - Main Area: Equipment
2 - Air Scrubbers
1 - 25 Ft Extension Cord



30. Second Floor - Main Area: Temperature And Humidity




31. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



32. Second Floor - Southeast Corner: Equipment


- 22 - Zip Post
- 6 - Air Scrubbers
- 1 - 50 Ft Extension Cord









33. Second Floor - Southeast Corner: Filter Change





34. Second Floor - Southeast Corner: Temperature and Humidity



35. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50 Ft Extension Cord




36. Third Floor - Main Area: Filter Change



37. Third Floor - Main Area: Temperature And Humidity



38. Main Entrance - Children's Area: Anti-Microbial Fog Treatment



39. Overall: Equipment

- 25 - Air Scrubbers
- 51 - Zip Post
- 3 - Foggers
- 3 - 50 Ft Extension Cords
- 2 - 25 Ft Extension Cords
- 2 - 20 Ft Conex