

Date Tue 01/30/2024

Job #

## Weather

6:00 AM

44° 

Clear

Wind: 6 MPH | Precipitation: .0" | Humidity: 75%

12:00 PM

64° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 43%

4:00 PM

68° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 40%

## Work Logs

Name	Description
Cavins Environmental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas, temperature and humidity readings were recorded. Clearance testing was performed in 311 local history, first floor bay windows and main entrance-Children's area. Finished cleaning phase 1 on second floor southeast corner.
Total	

## General Notes

### 1. Exterior: Equipment




### 2. Exterior: Temperature And Humidity



**3. Third Floor - Main Area: Equipment**  
1 - Air Scrubbers  
1 - 100' Extension Cords





**4. Third Floor - Main Area: Filter Change**






**5. Third Floor - Main Area: Temperature And Humidity**



**6. Second Floor - Main Area: Equipment**  
2 - Air Scrubbers  
1 - 25' Extension Cord




**7. Second Floor - Main Area: Filter Change**



**8. Second Floor - Main Area: Temperature And Humidity**




**9. Second Floor - Southeast Corner: Containment Upon Arrival/Departure**








10. Second Floor - Southeast Corner: Equipment  
 22 - Zip Posts  
 6 - Air Scrubbers  
 1 - 50' Extension Cord







11. Second Floor - Southeast Corner: Filter Change






**12. Second Floor - Southeast Corner: Temperature And Humidity**



**13. Second Floor - Southeast Corner: Finish Phase 1 Cleaning**  
 Finish wipe down with anti microbial solution and fog

**14. 149 Storytime: Containment Upon Arrival/Departure**



**15. 149 Storytime: Equipment**

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger



16. 149 Storytime: Filter Change




17. 149 Storytime: Temperature And Humidity












**18. First Floor - Main Area: Equipment**  
3 - Air Scrubbers  
1 - 25' Extension Cord




**19. First Floor - Main Area: Filter Change**







**20. First Floor - Main Area: Temperature And Humidity**



**21. First Floor - Bay Windows (Children's Area): Containment Upon Arrival/Departure**




**22. First Floor - Bay Windows (Children's Area): Equipment  
12 - Zip Posts**



**23. Main Entrance - Children's Area: Containment Upon Arrival/Departure**



**24. Main Entrance - Children's Area: Equipment  
10 - Zip Posts**



**25. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**




**26. First Floor - Southwest Vestibule: Equipment**

- 2 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger



**27. First Floor - Southwest Vestibule: Filter Change**




**28. First Floor - Southwest Vestibule: Temperature And Humidity**



- 29. Overall - Equipment:**  
51 - Zip Posts  
16 - Air Scrubbers  
2 - 50' Extension Cords  
2 - 25' Extension Cords  
3 - Foggers

- Overall- Equipment (actual)  
51 - Zip Posts  
18 - Air Scrubbers  
2 - 50' Extension Cords  
2 - 25' Extension Cords

**30. Second Floor- Southeast Corner: Anti Microbial Fog treatment**



- 31. 311 Local History: Equipment**  
2 - Air Scrubbers