

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 01/31/2024

Job #

## Weather

6:00 AM

40° 

Clear

Wind: 0 MPH | Precipitation: .0" | Humidity: 91%

12:00 PM

66° 

Clear

Wind: 11 MPH | Precipitation: .0" | Humidity: 42%

4:00 PM

72° 

Clear

Wind: 14 MPH | Precipitation: .0" | Humidity: 31%

## Work Logs

Name	Description
Cavins Environmental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas along with temperature and humidity readings. Started cleaning phase 2 on second floor southeast corner.
Total	

## General Notes

1. Exterior: Equipment  
2 - 20' Job Conex



2. Exterior: Temperature And Humidity



### 3. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




### 4. Second Floor - Southeast Corner: Equipment

- 22 - Zip Posts
- 6 - Air Scrubbers
- 1 - 50' Extension Cord
- 1 - Fogger













5. Second Floor - Southeast Corner: Filter Change







**6. Second Floor - Southeast Corner: Temperature And Humidity**



**7. Second Floor - Main Area: Equipment**  
2 - Air Scrubbers  
1 - 25' Extension Cord



**8. Second Floor - Main Area: Filter Change**





**9. Second Floor - Main Area: Temperature And Humidity**



**10. 149 Storytime: Containment Upon Arrival/Departure**




**11. 149 Storytime: Equipment**

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger





**12. 149 Storytime: Filter Change**



**13. 149 Storytime: Temperature And Humidity**











**14. First Floor - Main Area: Equipment**  
3 - Air Scrubbers  
1 - 25' Extension Cord



**15. First Floor - Main Area: Filter Change**







**16. First Floor - Main Area: Temperature And Humidity**




**17. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure**



**18. First Floor - Southwest Vestibule: Equipment**

- 2 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger







**19. First Floor - Southwest Vestibule: Filter Change**



**20. First Floor - Southwest Vestibule: Temperature And Humidity**





**21. Third Floor - Main Area: Equipment**

- 1 - Air Scrubber
- 1 - 50' Extension Cord








**22. Third Floor - Main Area: Filter Change**



**23. Third Floor - Main Area: Temperature And Humidity**



**24. Second Floor - Southeast Corner: Second Round of Cleaning**



- 25. Overall: Equipment**
- 29 - Zip Posts
  - 16 - Air Scrubbers
  - 2 - 50' Extension Cords
  - 2 - 25' Extension Cords
  - 3 - Foggers