

Date Thu 02/01/2024

Job #

Weather

6:00 AM

49° 

Partially cloudy

Wind: 7 MPH | Precipitation: .0" | Humidity: 74%

12:00 PM

67° 

Clear

Wind: 16 MPH | Precipitation: .0" | Humidity: 39%

4:00 PM

72° 

Clear

Wind: 18 MPH | Precipitation: .0" | Humidity: 33%

Work Logs

Name	Description
Cavins Enviromental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas along with temperature and humidity readings. A water investigation was conducted in the first-floor vestibule and mold remediation continued.
Total	

General Notes

1. Exterior: Equipment
2 - 20' Job Conex





2. Exterior: Temperature And Humidity



- 3. Third Floor - Main Area: Equipment
 - 1 - Air Scrubber
 - 1 - 50' Extension Cord





- 4. Third Floor - Main Area: Filter Change






- 5. Third Floor - Main Area: Temperature And Humidity



- 6. Second Floor - Main Area: Equipment
 - 2 - Air Scrubbers
 - 1 - 25' Extension Cord




7. Second Floor - Main Area: Filter Change



8. Second Floor - Main Area: Temperature And Humidity





9. Second Floor - Southeast Corner: Containment Upon Arrival/Departure





- 10. Second Floor - Southeast Corner: Equipment**
 22 - Zip Posts
 6 - Air Scrubbers
 1 - 50' Extension Cord
 1 - Fogger









11. Second Floor - Southeast Corner: Filter Change





12. Second Floor - Southeast Corner: Temperature And Humidity



13. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger





14. First Floor - Main Area: Equipment
 3 - Air Scrubbers
 1 - 25' Extension Cord








15. First Floor - Southwest Vestibule: Equipment
 2 - Zip Posts
 2 - Air Scrubbers
 1 - Fogger



16. 149 Storytime: Containment Upon Arrival/Departure




17. 149 Storytime: Filter Change



18. 149 Storytime: Temperature And Humidity



19. First Floor - Main Area: Filter Change




20. First Floor - Main Area: Temperature And Humidity



21. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



22. First Floor - Southwest Vestibule: Filter Change



23. First Floor - Southwest Vestibule: Temperature And Humidity



- 24. Overall: Equipment**
- 29 - Zip Posts
- 16 - Air Scrubbers
- 3 - Foggers
- 3 - 50' Extension Cords
- 2 - 25' Extension Cords

25. First Floor - Southwest Vestibule: Continued Microbial Growth Remediation



26. First Floor - Southwest Vestibule: Water Trail Investigation

