

Date Sun 02/04/2024

Job #

Weather

6:00 AM

49° 

Overcast

Wind: 7 MPH | Precipitation: .0" | Humidity: 95%

12:00 PM

52° 

Overcast

Wind: 17 MPH | Precipitation: .0" | Humidity: 83%

4:00 PM

48° 

Overcast


Wind: 15 MPH | Precipitation: .0" | Humidity: 92%

Work Logs

Name	Description
Cavins Environmental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas, temperature and humidity readings were recorded. Southeast corner antimicrobial fog treatment was applied.
Total	

General Notes

1. 149 Storytime: Containment Upon Arrival/Departure




2. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger



3. 149 Storytime: Filter Change



4. 149 Storytime: Temperature And Humidity



5. Exterior: Equipment
2 - 20' Job Cones



6. Exterior: Temperature And Humidity



7. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord



8. First Floor - Main Area: Filter Change



9. First Floor - Main Area: Temperature And Humidity





10. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



11. First Floor - Southwest Vestibule: Equipment
 2 - Air Scrubbers
 2 - Zip Posts
 1 - Fogger



12. First Floor - Southwest Vestibule: Filter Change







13. First Floor - Southwest Vestibule: Temperature And Humidity





14. Second Floor - Main Area: Equipment
2 - Air Scrubbers
1 - 25' Extension Cord



15. Second Floor - Main Area: Filter Change






16. Second Floor - Main Area: Temperature And Humidity





17. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



18. Third Floor - Main Area: Filter Change



19. Third Floor - Main Area: Temperature And Humidity



20. Second Floor - Southeast Corner: Containment Upon Arrival/Departure



21. Second Floor - Southeast Corner: Equipment





- 22 - Zip Posts
- 6 - Air Scrubbers
- 2 - 50' Extension Cords
- 1 - Fogger







22. Second Floor - Southeast Corner: Filter Change





23. Second Floor - Southeast Corner: Temperature And Humidity



24. Second Floor - Southeast Corner: Antimicrobial Fog Treatment



- 25. Overall: Equipment**
29 - Zip Posts
16 - Air Scrubbers
3 - Foggers
3 - 50' Extension Cords
2 - 25' Extension Cords