

Date Mon 02/05/2024

Job #

Weather

6:00 AM

41° 

Overcast

Wind: 14 MPH | Precipitation: .0" | Humidity: 89%

12:00 PM

46° 

Partially cloudy

Wind: 14 MPH | Precipitation: .0" | Humidity: 71%

4:00 PM

54° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 51%

Work Logs

Name	Description
Cavins Environmental	Cavins technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas, temperature and humidity readings were recorded. Southwest vestibule phase 1 cleaning and HEPA vacuuming. 149 Story time, Selective demo and phase 1 cleaning was performed. Southeast corner antimicrobial fog treatment applied.
Total	

General Notes

1. 149 Storytime: Containment Upon Arrival/Departure






2. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger
- 1 - Hepa Vacuum
- 1 - 50' Extension Cord



3. 149 Storytime: Filter Change





4. 149 Storytime: Temperature And Humidity



**5. Exterior: Equipment
2 - 20' Job Conex**








6. Exterior: Temperature And Humidity



**7. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord**



8. First Floor - Main Area: Filter Change



9. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



10. First Floor - Main Area: Temperature And Humidity



11. First Floor - Southwest Vestibule: Equipment

- 2 - Air Scrubbers
- 2 - Zip Posts
- 1 - Fogger
- 1 - Hepa Vacuum
- 1 - 50' Extension Cord




12. Second Floor - Main Area: Equipment

- 2 - Air Scrubbers
- 1 - 25' Extension Cord



13. First Floor - Southwest Vestibule: Filter Change



14. First Floor - Southwest Vestibule: Temperature And Humidity



15. Second Floor - Main Area: Filter Change



16. Second Floor - Main Area: Temperature And Humidity




17. Second Floor - Southeast Corner: Antimicrobial Fog Treatment






18. Second Floor - Southeast Corner: Containment Upon Arrival/Departure




19. Second Floor - Southeast Corner: Equipment


- 22 - Zip Posts
- 6 - Air Scrubbers
- 1- 50' Extension Cords
- 1 - Fogger





20. Second Floor - Southeast Corner: Filter Change





21. Second Floor - Southeast Corner: Temperature And Humidity





22. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord



23. Third Floor - Main Area: Filter Change




24. Third Floor - Main Area: Temperature And Humidity



**25. 149 Storytime: Selective demo
First Phase of cleaning**









**26. Third Floor - Balcony Entrance: Equipment
4 - Zip Posts**



27. First Floor - Southwest Vestibule: Phase One Hepa Vacuuming And Cleaning:





28. First Floor - Southwest Vestibule: Phase One Anti Microbial Fog Treatment



29. Overall: Equipment

29 - Zip Posts

16 - Air Scrubbers

2 - Hepa Vacuums

3 - Foggers

3 - 50' Extension Cords

2 - 25' Extension Cords