

Date Thu 02/08/2024

Job #

Weather

6:00 AM

52° 

Clear

Wind: 14 MPH | Precipitation: .0" | Humidity: 86%

12:00 PM

65° 

Clear

Wind: 21 MPH | Precipitation: .0" | Humidity: 31%

4:00 PM

68° 

Clear

Wind: 26 MPH | Precipitation: .0" | Humidity: 24%

Work Logs


Name	Description
Cavins Enviromental	Cavins's technician arrived on site, suited up in proper PPE, changed all pre-filters in common and contained areas, temperature and humidity readings were recorded. The containment on the 2nd floor Southeast corner was taken down and equipment was removed.
Total	

General Notes


1. Exterior: Equipment 2 - 20' Job Conex




2. Exterior: Temperature And Humidity



3. Third Floor - Main Area: Equipment
1 - Air Scrubber
1 - 50' Extension Cord



4. Third Floor - Main Area: Filter Change



5. Third Floor - Main Area: Temperature And Humidity



6. Third Floor - Stairwell Wall: Containment Upon Arrival/Departure



7. Third Floor - Stairwell Wall: Equipment



7 - Zip Posts

2 - Air Scrubbers

2 - Hepa Vacuums





2 - 50' Extension Cords

1 - Fogger






8. Third Floor - Stairwell Wall: Filter Change



9. Third Floor - Stairwell Wall: Temperature And Humidity



10. Third Floor - Stairwell Wall: Phase One Hepa Vacuuming And Cleaning



11. Second Floor - Main Area: Equipment
 2 - Air Scrubbers
 1 - 25' Extension Cord




12. Second Floor - Main Area: Filter Change




13. Second Floor - Main Area: Temperature And Humidity



14. Second Floor - Southeast Corner: Containment Removed









15. Second Floor - Southeast Corner: Equipment Removed
 22 - Zip Posts
 6 - Air Scrubbers
 2 - 50' Extension Cords
 2 - 100' Extension Cords



16. First Floor - Main Area: Equipment
 3 - Air Scrubbers
 1 - 25' Extension Cord



17. First Floor - Main Area: Filter Change



18. First Floor - Main Area: Temperature And Humidity



19. 149 Storytime: Containment Upon Arrival/Departure



20. 149 Storytime: Equipment

- 5 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger



21. 149 Storytime: Filter Change




22. 149 Storytime: Temperature And Humidity



23. 149 Storytime: Final Anti Microbial Fog Treatment




24. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure




25. First Floor - Southwest Vestibule: Equipment
 2 - Zip Posts
 2 - Air Scrubbers
 1 - Fogger



26. First Floor - Southwest Vestibule: Filter Change






27. First Floor - Southwest Vestibule: Temperature And Humidity





28. First Floor - Southwest Vestibule: Final Anti Microbial Fog Treatment



29. Third Floor - Stairwell Wall: Phase Two Hepa Vacuuming And Cleaning






30. Third Floor - Stairwell Wall: Phase One Anti Microbial Fog Treatment



31. Third Floor - Stairwell Wall: Phase Two Anti Microbial Fog Treatment



- 32. Overall: Equipment**
- 12 - Air Scrubbers
 - 14 - Zip Posts
 - 3 - 50' Extension Cords
 - 2 - 25' Extension Cords
 - 2 - Hepa Vacuums
 - 3 - Foggers