

Date Fri 02/09/2024

Job #

Weather

6:00 AM

44° 

Partially cloudy

Wind: 10 MPH | Precipitation: .0" | Humidity: 67%

12:00 PM

59° 

Clear

Wind: 13 MPH | Precipitation: .0" | Humidity: 47%

4:00 PM

65° 

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 33%

Work Logs

Name	Description
Cavins Group Environmental	Completed a fog treatment in stairwell, counted equipment, and changed the filters in all air scrubbers. Also completed post remediation testing and the removal of cleared containment and equipment.
Total	

General Notes

1. Exterior: Equipment
2 - 20' Job Conex





2. Exterior: Temperature And Humidity



- 3. Third Floor - Main Area: Equipment
 - 1 - Air Scrubbers
 - 1 - 50' Extension Cord



- 4. Third Floor - Main Area: Filter Change




- 5. Third Floor - Main Area: Temperature And Humidity



- 6. Third Floor - Stairwell Wall: Containment Upon Arrival/Departure



7. Third Floor - Stairwell Wall: Equipment
 7 - Zip Posts
 2 - Air Scrubbers
 1 - Fogger




8. Third Floor - Stairwell Wall: Filter Change





9. Third Floor - Stairwell Wall: Temperature And Humidity



**10. First Floor - Vestibule/Newspaper Area
Post Remediation Verification Testing
One spore trap sample was taken**





11. Third Floor - Stairwell Wall: Anti Microbial Fog Treatment



12. Second Floor - Main Area: Equipment
 2 - Air Scrubbers
 1 - 25' Extension Cord




13. Second Floor - Main Area: Filter Change



14. Second Floor - Main Area: Temperature And Humidity



15. First Floor - Room 149
Post Remediation Verification Testing
One spore trap sample taken



16. Exterior Control Sample












17. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord




18. First Floor - Main Area: Filter Change





19. First Floor - Main Area: Temperature And Humidity



20. 149 Storytime: Containment Upon Arrival/Departure



**21. 149 Storytime: Equipment
5 - Zip Posts**





22. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure



**23. First Floor - Southwest Vestibule: Equipment
2 - Zip Posts**



24. Overall: Equipment
14 - Zip Posts
8 - Air Scrubbers
1 - 50' Extension Cord
2 - 25' Extension Cords
1 - Fogger

25. 149 Storytime: Containment Removed



26. 149 Storytime: Equipment Removed
2 - Air Scrubbers
5 - Zip Posts



27. Facility:
Cavins technicians removed the excess tape and cleaned the library.

