

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Sat 02/10/2024

Job #

Weather

6:00 AM

42° 

Clear

Wind: 9 MPH | Precipitation: .0" | Humidity: 80%

12:00 PM

48° 

Partially cloudy

Wind: 10 MPH | Precipitation: .0" | Humidity: 60%

4:00 PM

52° 

Partially cloudy

Wind: 17 MPH | Precipitation: .0" | Humidity: 54%

Work Logs

Name	Description
Cavins Group Environmental	Completed fog treatment in the stairwell, counted equipment, and changed all filters in air scrubbers.
Total	



General Notes

1. Third Floor - Stairwell Wall: Temperature And Humidity




2. Third Floor - Stairwell Wall: Filter Change






3. Third Floor - Stairwell Wall: Equipment
7 - Zip Posts
2 - Air Scrubbers
1 - Fogger



4. Third Floor - Stairwell Wall: Containment Upon Arrival/Departure



5. Exterior: Equipment
2 - 20' Job Conex




6. Exterior: Temperature And Humidity



7. First Floor - Main Area: Equipment
3 - Air Scrubbers
1 - 25' Extension Cord




8. First Floor - Main Area: Filter Change



9. First Floor - Main Area: Temperature And Humidity



10. First Floor - Southwest Vestibule: Containment Upon Arrival/Departure





- 11. Overall: Equipment**
- 14 - Zip Posts
- 8 - Air Scrubbers
- 1 - 50' Extension Cord
- 2 - 25' Extension Cords
- 1 - Fogger

- 12. First Floor - Southwest Vestibule: Equipment**
- 2 - Zip Posts



- 13. Second Floor - Main Area: Equipment**
- 2 - Air Scrubbers
- 1 - 25' Extension Cord



- 14. Second Floor - Main Area: Filter Change**



15. Second Floor - Main Area: Temperature And Humidity



16. Third Floor - Main Area: Equipment

- 1 - Air Scrubbers
- 1 - 50' Extension Cord



17. Third Floor - Main Area: Filter Change



18. Third Floor - Main Area: Temperature And Humidity



19. Third Floor - Stairwell Wall: Anti Microbial Fog Treatment

