

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Mon 02/12/2024

Job #

Weather

6:00 AM

34°

Overcast

Wind: 11 MPH | Precipitation: .0" | Humidity: 93%

12:00 PM

42°

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 70%

4:00 PM

48°

Clear


Wind: 11 MPH | Precipitation: .0" | Humidity: 56%


Work Logs

Name	Description
Cavins Group Environmental	Cavins Group completed the removal of some containments, counted equipment, and changed the filters in the air scrubbers.
Total	

General Notes

1. Third Floor - Balcony/Stairwell Door
One spore trap sample taken in containment.
Signs of ongoing roof leaks and water intrusion.








2. Exterior - Control Sample
One spore trap sample was taken.



3. Containment taken down from first floor Southwest Vestibule






4. First Floor - Main Area: Filter Change



5. Third Floor - Main Area: Filter Change



6. Second Floor - Main Area: Filter Change



7. Third Floor - Stairwell Wall: Filter Change



8. Third Floor - Stairwell Wall: Equipment

- 7 - Zip Posts
- 2 - Air Scrubbers
- 1 - Fogger

9. Third Floor - Main Area: Equipment

- 1 - Air Scrubbers
- 1 - 50' Extension Cord

- 10. Exterior: Equipment**
 - 2 - 20' Job Conex
- 11. Second Floor - Main Area: Equipment**
 - 2 - Air Scrubbers
 - 1 - 25' Extension Cord
- 12. First Floor - Main Area: Equipment**
 - 3 - Air Scrubbers
 - 1 - 25' Extension Cord
- 13. Overall: Equipment**
 - 7 - Zip Posts
 - 8 - Air Scrubbers
 - 2 - 25' Extension Cords
 - 1 - 50' Extension Cord