

Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Wed 02/21/2024

Job #

Weather

6:00 AM

50°

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 80%

12:00 PM

74°

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 28%

4:00 PM

81°

Clear


Wind: 13 MPH | Precipitation: .0" | Humidity: 23%

Work Logs

Name	Description
Cavins Environmental	Cavins technician assisted water testing on the First Floor - Southwest Vestibule, and SO 115. Air scrubbers' equipment counts. recorded.
Total	

General Notes

1. First Floor - Southwest Vestibule: Water Testing



2. Equipment: 1 - 150' boom lift




3. First Floor - Main Area: Equipment
2 - Air Scrubbers



4. Second Floor - Main Area: Equipment
1 - Air Scrubber
1 - 25' Extension Cord



5. Third Floor - Main Area: Equipment
1 - Air Scrubber
1 - 25' Extension Cord



6. SO 115: Water Testing





7. First Floor - Main Area: Temperature and Humidity



8. Second Floor - Main Area: Temperature and Humidity



9. Third Floor - Main Area: Temperature and Humidity

