

# Norman Public Library Central - Mold

103 W Acres St Norman, OK 73069



Date Mon 02/26/2024

Job #

## Weather

6:00 AM

48°

Clear

Wind: 8 MPH | Precipitation: .0" | Humidity: 65%

12:00 PM

78°

Clear

Wind: 12 MPH | Precipitation: .0" | Humidity: 23%

4:00 PM

88°

Clear



Wind: 24 MPH | Precipitation: .0" | Humidity: 17%


## Work Logs

Name	Description
Cavins Group Environmental	Cavins technician assisted consultants with water testing of stairwell wall, carried and set up extension ladder where needed. Also, safely assisted with the moving of the boom lift and its operations.
Total	





## General Notes

### 1. Water Testing Stairwell Wall





## 2. Boom Lift Operations



## 3. Equipment On Site



### 4. Third Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 50' Extension Cord

### 5. Second Floor - Main Area: Equipment

- 1 - Air Scrubber
- 1 - 25' Extension Cord

### 6. First Floor - Main Area: Equipment

- 3 - Air Scrubbers
- 1 - 25' Extension Cord